



Inspection Type: Annual Inspection																
Site ID Site Name	Site Reference	Site Archived	Item ID Item Type	ltem	Part Number	Item Archive		Life Expectancy	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer	Finding Item Photo Pho
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1043700 Rotor Play 1043687 Swings	Overhead Rotator 2 Bay (2 Flat, 2 Cradle)	2.8m Traditional S		15/07/2025			2 The surfacing is severely damaged	Repair damaged areas of surfacing	12	Maintenance	No Grass Matrix Tiles	Playdale Playgrounds Ltd	<u>Yes</u> <u>Ye</u>
88053 Broomfield Recreation Ground		No	1043682 Swings	Surf Swing	2.8m Traditional S	win No No				The chain links are worn excessively and require renewing The seat is severely damaged and requires replacing	Replace worn chains Replace damaged seat	12 12	Maintenance Maintenance	No Wet Pour No Grass Matrix Tiles	Wicksteed Playgrounds Playdale Playgrounds Ltd	Yes Ye Yes Ye
88053 Broomfield Recreation Ground		No	1043682 Swings	Surf Swing		No	15/07/2025		67797077	7 The surfacing is severely damaged	Repair damaged areas of surfacing	12	Maintenance	No Grass Matrix Tiles	Playdale Playgrounds Ltd	Yes Ye
88057 Knockhall Recreation Ground		No	1043748 Swings	2 Bay (2 Flat, 2 Cradle)	2.3m Swing	No	15/07/2025		67797450	There are significant gaps (over 30mm) between the surface and the edging or between the joints in the surface; these are large enough for a small foo		12	Maintenance	No Wet Pour	Caloo	<u>Yes</u> <u>Ye</u>
88055 Manor Park		No	1043735 Rotor Play	Roundabout	Honeycomb Whirl	No	15/07/2025		67797352	to enter  The plate beneath the platform is loose	Secure	12	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Ye
88055 Manor Park		No	1043735 Rotor Play	Roundabout	Honeycomb Whirl	No	15/07/2025		67707746							
88055 Manor Park		No	1043734 Swings	1 Bay 2 Seat (Flat)	2.1m Double Arch					3 The surface has worn thin around the item exposing concrete foundations 7 There are significant gaps (over 30mm) between the surface and the edging or between the joints in the surface; these are large enough for a small foo to enter	Repair surfacing	12	Maintenance Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes Ye Yes Ye
88054 Swanscombe Park 88054 Swanscombe Park		No No	1043716 Activity Equipment 1043724 Swings	Swinging Steps 1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No No	15/07/2025 15/07/2025			There are areas or parts of the timber on the structure that have rotted and the seat is severely damaged and requires replacing	Replace all rotted timbers Replace damaged seat	12	Maintenance	No Grass	Playdale Playgrounds Ltd	<u>Yes</u> <u>Ye</u>
88054 Swanscombe Park			1043724 Swings	1 Bay 2 Seat (Cradle)								12	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	<u>Yes</u> <u>Ye</u>
		140		1 Bay 2 Seat (Claule)	1.8m Timber Swing	g NO	15/07/2025		6//9/194	4 One of the posts have rotted and the remaining timber is showing signs of rot	Replace all rotted timber	12	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	<u>Yes</u> <u>Ye</u>
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1043704 Activity Equipment 1043693 Multi Use Games Area	Trapeze Rings Basketball Post		No No	15/07/2025 15/07/2025			A number of fixing(s) have worked loose The net is damaged and requires removal / replacement	Secure all loose fixings Replace	10 10	Maintenance Maintenance	No Grass Matrix Tiles No Tarmac	Playdale Playgrounds Ltd Adidas	<u>Yes</u> <u>Ye</u> <u>Yes</u> <u>Ye</u>
88053 Broomfield Recreation Ground		No	1043698 Rocking Equipment	Spring Bike		No	15/07/2025		67797123	The grass has eroded within the impact area of the equipment and may not		10	Maintenance	No Mixed Surface	Playdale Playgrounds Ltd	Yes Ye
88053 Broomfield Recreation Ground  88053 Broomfield Recreation Ground		No No	1043698 Rocking Equipment  1043700 Rotor Play	Spring Bike Overhead Rotator		No	15/07/2025 15/07/2025			The spring rotates on the base	Secure spring to prevent rotation	10	Maintenance	No Mixed Surface	Playdale Playgrounds Ltd	Yes Ye
88053 Broomfield Recreation Ground		No	1043687 Swings	2 Bay (2 Flat, 2 Cradle)	2.8m Traditional S	No win No				The shackles are worn in excess of 40% and require renewing The bush / bushes is / are worn or missing	Replace worn shackles Replace worn or missing bushes	10	Maintenance Maintenance	No Grass Matrix Tiles No Wet Pour	Playdale Playgrounds Ltd Wicksteed Playgrounds	Yes Ye No Ye
88059 Eagles Road Play Area		No	1043795 Activity Equipment	Rotating Beam		No	16/07/2025		67797525	All of the fixings are missing from the support plate at one end of the beam	Replace all missing fixings	10	Maintenance	No Grass Matrix Tiles	A.E.Evans	Yes Ye
Eagles Road Play Area Eagles Road Play Area		No No	1043794 Gates 1043800 Gates	Gate - Combination Gate - Self Closing		No No	16/07/2025 16/07/2025		67797531 67797568	There are openings that are less than 12mm that could trap or crush fingers There are openings that are less than 12mm that could trap or crush fingers	Frovide a 12mm gap throughout full range of motion at both sides of gate	10	Installation	No Mixed Surface	Unknown	Yes Ye
88057 Knockhall Recreation Ground		No	1043748 Swings	2 Bay (2 Flat, 2 Cradle)	2.3m Swing	No	15/07/2025		67797453	3 The chain links are worn excessively and require renewing	Replace worn chains	10	Installation Maintenance	No Mixed Surface No Wet Pour	Unknown Caloo	Yes Yes
88055 Manor Park 88060 Saxon Court Play Area		No No	1043737 Activity Equipment 1043817 Gates	Multi Play (Junior) Gate - Combination		No No	15/07/2025 15/07/2025		67797320	There are areas or parts of the timber on the structure that have rotted There are openings that are less than 12mm that could trap or crush fingers	Replace all affected timbers	10	Maintenance	No Wet Pour	Setter Play	Yes Ye
			1042025 - C-1									10	Installation	No Tarmac	Unknown	<u>Yes</u> <u>Ye</u>
88060 Saxon Court Play Area 88060 Saxon Court Play Area		No No	1043825 Gates 1043820 Swings	Gate - Self Closing 1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.3m Swing	No No	15/07/2025 15/07/2025			There are openings that are less than 12mm that could trap or crush fingers There are significant gaps (over 30mm) between the surface and the edging		10	Installation Maintenance	No Tarmac No Wet Pour	Unknown Caloo	No Ye
88054 Swanscombe Park		No	1043721 Activity Equipment	Balance Beam	Inclined Balance B	ean No	15/07/2025		67797245	There are areas or parts of the timber on the structure that have rotted and	Replace all rotted timbers	10	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes Yes
88054 Swanscombe Park 88054 Swanscombe Park		No No	1043712 Activity Equipment 1043727 Activity Equipment	Bridge Burma Bridge		No No	15/07/2025 15/07/2025			There are areas or parts of the timber on the structure that have rotted and		10	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes Yes
88054 Swanscombe Park		No	1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025			The chain links are worn excessively and require renewing There are areas or parts of the timber on the structure that have rotted	Replace worn chains Replace all affected timbers	10 10	Maintenance Maintenance	No Grass No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes
88054 Swanscombe Park 88054 Swanscombe Park		No	1043716 Activity Equipment	Swinging Steps		No	15/07/2025		67797258	The chain links are worn excessively and require renewing	Replace worn chains	10	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes Ye
88054 Swanscombe Park 88058 Valley View Play Area		No No	1043711 Other 1043778 Swings	Free Standing Slide  1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch	No h Sv No	15/07/2025 16/07/2025			The slide run-out support has corroded excessively and broken There are significant gaps (over 30mm) between the surface and the edging	Repair or replace as required	10 10	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Yes
		12-								or between the joints in the surface; these are large enough for a small foot to enter		10	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Ye
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1458817 Ancillary Items 1043700 Rotor Play	Site General Overhead Rotator		No No	15/07/2025 15/07/2025			3 There are significant gaps (over 30mm) between the surface and the edging 3 The handgrips have been damaged	Repair surfacing	9	Maintenance	No N/A	Owner/Operator	Yes Ye:
88059 Eagles Road Play Area		No	1043788 Fences	Fencing - Timber		No	16/07/2025			There are areas or parts of the timber on the fencing that have rotted and	Remove the projecting fixings and replace all affected timbers	9	Maintenance Maintenance	No Grass Matrix Tiles No Grass	Playdale Playgrounds Ltd Unknown	<u>Yes</u> <u>Yes</u> <u>Yes</u> <u>Ye</u> s
88057 Knockhall Recreation Ground		No	1043754 Activity Equipment	Climbing Frame		No	15/07/2025		67797479	There are significant gaps (over 30mm) between the surface and the edging or between the joints in the surface; these are large enough for a small fool		9	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Yes
88057 Knockhall Recreation Ground		No	1043746 Gates	Kissing Gate		No	15/07/2025			to enter  The item has been damaged	Repair or replace the item / affected part	9	Maintenance	No Paving Slabs	Unknown	Yes Yes
88057 Knockhall Recreation Ground		No	1043746 Gates	Kissing Gate		No	15/07/2025		67797482	Parts of the steel on this item have corroded excessively and the metal has perforated in places	Ensure all affected areas are treated and repaired	9	Maintenance	No Paving Slabs	Unknown	No Ye
88057 Knockhall Recreation Ground		No	1043751 Other	Free Standing Slide		No				There are significant gaps (over 30mm) between the surface and the edging	Repair surfacing	9	Maintenance .	No Wet Pour	Wicksteed Playgrounds	Yes Yes
88060 Saxon Court Play Area 88060 Saxon Court Play Area		No No	1043829 Activity Equipment 1043810 Activity Equipment	Burma Bridge Rope Traverse	Parallel Rope Trave	No erse No	15/07/2025 15/07/2025			The rope has worn and wire strands are exposed The rope has worn and wire strands are exposed	Replace rope or net	9	Maintenance	No Grass	Unknown	Yes Ye:
88060 Saxon Court Play Area		No	1043823 Activity Equipment	Rope Traverse	Cross Rope Travers					The rope has worn and wire strands are exposed	Replace rope or net Replace rope or net	9	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	<u>Yes</u> <u>Yes</u> <u>Yes</u> <u>Ye</u> s
88054 Swanscombe Park		No	1043709 Rocking Equipment	See Saw	LNB Seesaw	No	15/07/2025		67797215	Parts of the steel on this item have corroded excessively and the metal has perforated in places	Ensure all affected areas are treated and repaired	9	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Yes
88053 Broomfield Recreation Ground		No	1043689 Activity Equipment	Climbing Frame	Delta Climber	No	15/07/2025		67797114	Perforated in places In There is/are finger entrapment/s in the frame due to missing components and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6	Replace all missing components	8	Compliance	No Wet Pour	Wicksteed Playgrounds	Yes Yes
88053 Broomfield Recreation Ground		No	1043685 Activity Equipment	Multi Play (Junior)		No	15/07/2025		67797136	The surface is lifting at the edges and creating trip points	Repair perimeter of surfacing to remove trip points	8	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes Yes
P Broomfield Recreation Ground Broomfield Recreation Ground		No No	1043704 Activity Equipment 1458817 Ancillary Items	Trapeze Rings Site General		No No	15/07/2025 15/07/2025			I The grass mats are silted up, the soil is compacted and the area will become E Parts of the timber edging has rotted	e Reinstate as required Replace all affected timber	8	Maintenance Maintenance	No Grass Matrix Tiles No N/A	Playdale Playgrounds Ltd Owner/Operator	Yes Yes
88053 Broomfield Recreation Ground		No	1458817 Ancillary Items	Site General		No	15/07/2025		67797097	The bitumen surface is worn or damaged	Repair the bitumen to provide a uniform surface	8	Maintenance	No N/A	Owner/Operator	Yes Yes
88053 Broomfield Recreation Ground		No	1458817 Ancillary Items	Site General		No	15/07/2025		67797099	The surface is lifting at the edges and creating trip points	Repair perimeter of surfacing to remove trip points	8	Maintenance	No N/A	Owner/Operator	Yes Yes
88053 Broomfield Recreation Ground		No	1043691 Gates	Gate - Self Closing		No	15/07/2025		67797093	The area under the gate has eroded leaving uneven areas, or the concrete foundations exposed, resulting in trip hazards at the entrance/exit to the	Reinstate to level with surrounding surfaces	8	Maintenance	No Paving Slabs	Unknown	Yes Yes
88053 Broomfield Recreation Ground		No	1043693 Multi Use Games Area	Basketball Post		No	15/07/2025		67797068	There are trip hazards at the edges of the surface	Remove trip hazard	8	Maintenance	No Tarmac	Adidas	Yes Yes
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1043681 Outdoor Fitness Equipment 1043688 Outdoor Fitness Equipment	Air Walker Chest Press		No No	15/07/2025 15/07/2025			The grass mats are silted up, the soil is compacted and the area will become The grass mats are silted up, the soil is compacted and the area will become		8	Maintenance	No Grass Matrix Tiles	Caloo	Yes Yes
88053 Broomfield Recreation Ground		No	1043686 Outdoor Fitness Equipment	Shoulder Press		No				very slippery when the soil is wet.  The grass mats are silted up, the soil is compacted and the area will become		8	Maintenance	No Grass Matrix Tiles	Caloo	Yes Yes
88053 Broomfield Recreation Ground		No	1043690 Outdoor Fitness Equipment	Skier		No				very slippery when the soil is wet.  The grass mats are sitted up, the soil is compacted and the area will become	and the second s	8	Maintenance	No Grass Matrix Tiles	Caloo	Yes Yes
										very slippery when the soil is wet.		•	Maintenance	No Grass Matrix Tiles	Caloo	Yes Yes
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1043692 Rocking Equipment 1043698 Rocking Equipment	Four Way Springer Spring Bike		No No	15/07/2025 15/07/2025			The surfacing dimensions are short and do not meet with the requirements The spring clamps are loose	Monitor - No action given the risk assessment Tighten all loose fixings	8	Compliance Maintenance	No Wet Pour No Mixed Surface	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes
88053 Broomfield Recreation Ground		No	1043696 Rocking Equipment	Spring Bike		No	15/07/2025			There is some evidence of fire damage to the surfacing	Monitor for any further deterioration and repair as required	8	Vandalism	No Mixed Surface	Ledon	Yes Yes
88053 Broomfield Recreation Ground		No	1043696 Rocking Equipment	Spring Bike		No	15/07/2025		67797128	The grass has eroded within the impact area of the equipment and may not provide the necessary impact attenuating properties for the equipment fall	Reinstate the grass or provide an all weather surface	8	Maintenance	No Mixed Surface	Ledon	Yes Yes
88053 Broomfield Recreation Ground 88053 Broomfield Recreation Ground		No No	1043700 Rotor Play 1043682 Swings	Overhead Rotator Surf Swing		No				. The grass mats are silted up and the soil is compacted; this may have an		8	Maintenance	No Grass Matrix Tiles	Playdale Playgrounds Ltd	Yes Yes
88053 Broomfield Recreation Ground		No	1043682 Swings	Surf Swing		No No				The grass mats are slited up and the soil is compacted; this may have an BS EN 1176 Part 1 - 4.2.6 states that where moving parts are provided that can endanger the body, there shall be a ground clearance of at least 400mm, and this has not been provided		8	Maintenance Compliance	No Grass Matrix Tiles No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes Yes Yes
88059 Eagles Road Play Area		No	1043795 Activity Equipment	Rotating Beam		No			67797524	The timber has a number of splits/shakes or air cracks and this may affect	Monitor to ensure the splits do not cross through fixing points of the	8	Maintenance	No Grass Matrix Tiles	A.E.Evans	Yes Yes
88059 Eagles Road Play Area 88059 Eagles Road Play Area		No No	1043807 Fences 1043794 Gates	Fencing - Timber Gate - Combination		No			67797544	The fence is damaged in places	Repair or replace all affected sections	8	Maintenance	No Grass	Unknown	Yes Yes
88059 Eagles Road Play Area 88059 Eagles Road Play Area		No No	1043794 Gates 1043800 Gates	Gate - Combination Gate - Self Closing		No No				The area under the gate has eroded leaving uneven areas, or the concrete The area under the gate has eroded leaving uneven areas, or the concrete		8	Maintenance Maintenance	No Mixed Surface	Unknown	Yes Yes
88059 Eagles Road Play Area		No	1043804 Gates	Kissing Gate		No				The area under the gate has evoded leaving uneven areas, or the concrete The area under the gate has evoded leaving uneven areas, or the concrete foundations exposed, resulting in trip hazards at the entrance/exit to the playground		8	Maintenance Maintenance	No Mixed Surface No Soil	Unknown Unknown	Yes Yes Yes Yes
88059 Eagles Road Play Area		No	1043802 Swings	Basket Swing - Type 1	2.3m Timber Swing		16/07/2025		67797549	The timber has a number of splits/shakes or air cracks and this may affect	Monitor to ensure the splits do not cross through fixing points of the	8	Maintenance	No Grass Matrix Tiles	A.E.Evans	Yes Yes
88059 Eagles Road Play Area 88056 Heritage Park		No No	1043802 Swings 1186749 Activity Equipment	Basket Swing - Type 1 Activity Trail	2.3m Timber Swing	No No			67797550	The grass mats are silted up and the soil is compacted; this may have an	Contact our office for a quotation for this service	8	Maintenance	No Grass Matrix Tiles	A.E.Evans	Yes Yes
		110	22307-35 Activity Equipment	Country (1811		NO	15/01/2025		0//9/1/4	The grass has eroded within the impact area of the equipment and may not	nemistate the grass or provide an all weather surface	8	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes Yes



Site ID Site Name	Site Reference	Site Archived	Item ID Item Type	Item	Part Number	Item Archived	Inspection Date	Life Expectancy	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Sur	rface	Manufacturer		Item Photo
88056 Heritage Park		No	1186760 Gates	Gate - Combination		No	15/07/2025		67797169	The area under the gate has eroded leaving uneven areas, or the concrete foundations exposed, resulting in trip hazards at the entrance/exit to the playground	Reinstate to level with surrounding surfaces	8	Maintenance	No Mix	xed Surface	Unknown	Yes	Yes
88056 Heritage Park			1186740 Gates	Gate - Self Closing		No	15/07/2025		67797164	The area under the gate has eroded leaving uneven areas, or the concrete	Reinstate to level with surrounding surfaces	8	Maintenance	No Mix	xed Surface	Unknown	Yes	Yes
88057 Knockhall Recreation Ground 88057 Knockhall Recreation Ground		No No	1043759 Activity Equipment 1043759 Activity Equipment	Multi Play (Senior) Multi Play (Senior)		No No	15/07/2025 15/07/2025			Parts of the timber edging has rotted A number of fixing(s) have worked loose	Replace all affected timber	8	Maintenance		et Pour	Playdale Playgrounds Ltd	No	Yes
88057 Knockhall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797461	There are splits in the timber running through fixing points and creating	Secure all loose fixings Replace all affected timber parts	8	Maintenance Maintenance		et Pour et Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	Yes
88057 Knockhall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797462	The timber has a number of splits/shakes or air cracks and this may affect	Monitor to ensure the splits do not cross through fixing points of the	8	Maintenance		et Pour	Playdale Playgrounds Ltd	Yes	Yes
88057 Knockhall Recreation Ground 88057 Knockhall Recreation Ground		No No	1043759 Activity Equipment  1043752 Activity Equipment	Multi Play (Senior)  Multi Play (Toddler)		No No	15/07/2025 15/07/2025			There is some instability within the structure	Secure all loose fixings and monitor	8	Maintenance		et Pour	Playdale Playgrounds Ltd	Yes	Yes
Middle Medical of Good		110	1043732 Activity Equipment	Walti Flay (Todaler)		NO	15/07/2025		67/9/445	There is or are fixings missing on the item	Replace all missing fixings	8	Maintenance	No We	et Pour	Playdale Playgrounds Ltd	Yes	Yes
88057 Knockhall Recreation Ground			1458821 Ancillary Items	Site General		No	15/07/2025		67797440	There are trip hazards at the edges of the surface	Remove trip hazard	8	Maintenance	No N/A	A	Owner/Operator	Yes	Yes
88057 Knockhall Recreation Ground 88057 Knockhall Recreation Ground			1458821 Ancillary Items 1043765 Gates	Site General		No	15/07/2025			The surface is lifting at the edges and creating trip points	Repair perimeter of surfacing to remove trip points	8	Maintenance	No N/A		Owner/Operator	Yes	Yes
88057 Knockhall Recreation Ground			1043765 Gates	Gate - Self Closing  Gate - Self Closing		No No	15/07/2025 15/07/2025			The area under the gate has eroded leaving uneven areas, or the concrete foundations exposed, resulting in trip hazards at the entrance/exit to the The gate is closing too quickly (less than 4 seconds)		8	Maintenance	No Pav		Unknown	Yes	Yes
88057 Knockhall Recreation Ground		No	1043746 Gates	Kissing Gate		No	15/07/2025			There are trip hazards at the edges of the surface	Take corrective action to ensure that the gate closes in 4-8 seconds from 90 Remove trip hazard	8	Maintenance Maintenance	No Pav No Pav		Unknown Unknown	Yes Yes	Yes Yes
88057 Knockhall Recreation Ground 88057 Knockhall Recreation Ground		No	1043751 Other	Free Standing Slide	111 H	No	15/07/2025		67797473	There are projecting bolt thread(s) present	Remove excess thread length and deburr or provide cap	8	Maintenance	No We		Wicksteed Playgrounds	Yes	Yes
18055 Manor Park		No No	1043748 Swings 1043737 Activity Equipment	2 Bay (2 Flat, 2 Cradle) Multi Play (Junior)	2.3m Swing	No No	15/07/2025 15/07/2025			There is moderate damage to the surface There is moderate damage to the surface	Repair the damaged areas of surfacing	8	Maintenance	No We		Caloo	Yes	Yes
88055 Manor Park		No	1043737 Activity Equipment	Multi Play (Junior)		No	15/07/2025			The stepping head forms a projecting obstacle / hard object within the	Repair the damaged areas of surfacing  Monitor - No action given the risk assessment	8	Maintenance Compliance		et Pour et Pour	Setter Play Setter Play	Yes Yes	Yes Yes
18055 Manor Park 18055 Manor Park		No	1458819 Ancillary Items	Site General		No	15/07/2025		67797316	The surface is lifting at the edges and creating trip points	Repair perimeter of surfacing to remove trip points	8	Maintenance	No N/A		Owner/Operator	Yes	Yes
18055 Manor Park		No No	1458819 Ancillary Items 1458819 Ancillary Items	Site General Site General		No	15/07/2025			There are trip hazards at the edges of the surface	Remove trip hazard	8	Maintenance	No N/A		Owner/Operator	Yes	Yes
18055 Manor Park			1043738 Fences	Site General Fence - Chainlink		No No	15/07/2025 15/07/2025			There are holes in the surface that may cause users to trip or roll ankles The fence post has been severely damaged	Infill to provide a sound reasonably level surface. Replace all affected posts	8	Maintenance Maintenance	No N/A No Gra		Owner/Operator Unknown	Yes Yes	Yes Yes
8055 Manor Park			1043733 Gates	Gate - Self Closing		No	15/07/2025			The gate is closing too quickly (less than 4 seconds)	Take corrective action to ensure that the gate closes in 4-8 seconds from 90 degrees	8	Maintenance	No Tari		Not Identified	Yes	
8055 Manor Park		No	1043736 Rocking Equipment	Spring Motorbike		No	15/07/2025		67797328	A number of fixing(s) have worked loose	Secure all loose fixings	8	Maintenance	No We	et Pour	Wicksteed Playgrounds	Yes	Yes
8055 Manor Park		No	1043735 Rotor Play	Roundabout	Honeycomb Whirl	No	15/07/2025		67797346	There is/are finger entrapment/s in the platform due to missing fixings and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6	d Replace all missing fixings	8	Compliance	No We	et Pour	Wicksteed Playgrounds	Yes	Yes
8060 Saxon Court Play Area		No	1043826 Activity Equipment	Balance Beam	Inclined Balance Bean	No	15/07/2025		67797365	Entrapment of fingers There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Unknown	Yes	Yes
8060 Saxon Court Play Area		No	1043828 Activity Equipment	Balance Beam		No	15/07/2025		67797378	There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Unknown	Yes	Yes
8060 Saxon Court Play Area		No	1043829 Activity Equipment	Burma Bridge		No	15/07/2025		67797385	There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Unknown	Yes	Yes
8060 Saxon Court Play Area		No	1043831 Activity Equipment	Multi Play (Junior)	Zigzag Tower & Slide	No	15/07/2025			This item has no slide bar fitted as required by BS EN 1176 Part 3	Monitor - No action given the risk assessment	8	Compliance		et Pour	Wicksteed Playgrounds	Yes	Yes
8060 Saxon Court Play Area		No	1043831 Activity Equipment	Multi Play (Junior)	Zigzag Tower & Slide	No	15/07/2025		67797407	There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4		8	Compliance	No We	et Pour	Wicksteed Playgrounds	Yes	Yes
8060 Saxon Court Play Area		No	1043818 Activity Equipment	Wobble Board		No	15/07/2025		67797372	The surface has eroded and the foundations are exposed	Reinstate surrounding surfaces to cover the foundations	8	Maintenance	No Gra	ass	Unknown	Yes	Yes
8060 Saxon Court Play Area		No	1458824 Ancillary Items	Site General		No	15/07/2025		67797360	The surface is lifting at the edges and creating trip points	Repair perimeter of surfacing to remove trip points	8	Maintenance	No N/A	A	Owner/Operator	Yes	Yes
8060 Saxon Court Play Area 8060 Saxon Court Play Area			1458824 Ancillary Items 1458824 Ancillary Items	Site General Site General		No No	15/07/2025 15/07/2025			The bitumen surface is worn or damaged There are trip hazards at the edges of the drain covers	Repair the bitumen to provide a uniform surface Remove trip hazard	8	Maintenance Maintenance	No N/A		Owner/Operator Owner/Operator	Yes Yes	Yes Yes
8060 Saxon Court Play Area		No	1458824 Ancillary Items	Site General		No	15/07/2025		67797418	There are trip hazards at the edges of the surface	Remove trip hazard	8	Maintenance	No N/A	A	Owner/Operator	Yes	Yes
8060 Saxon Court Play Area		No	1043825 Gates	Gate - Self Closing		No	15/07/2025		67797395	There is moderate damage to the surface	Repair the damaged areas of surfacing	R	Maintenance	No Tarr	rmac	Unknown	Yes	Yes
8060 Saxon Court Play Area		No	1186765 Rotor Play	Rotating Net			15/07/2025			This item is satisfactory - no work required	report the duringed areas of surfacing					Wicksteed Playgrounds		
												•	Satisfactory	NO Gra	ass Matrix Tiles	Wicksteed Playgrounds	Yes	Yes
8060 Saxon Court Play Area 8054 Swanscombe Park			1043820 Swings 1043708 Activity Equipment	1 Bay Mixed Seat, 1 Cradle, 1 Flat A Frame Climber	2.3m Swing	No No	15/07/2025 15/07/2025			There is moderate damage to the surface There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176		8	Maintenance Compliance	No We		Caloo Wicksteed Playgrounds	<u>Yes</u> <u>Yes</u>	Yes Yes
8054 Swanscombe Park .		No	1043712 Activity Equipment	Bridge		No	15/07/2025		67797275	Part 1; 4.2.8.4 There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
8054 Swanscombe Park		No	1043730 Activity Equipment	Chain Traverse		No	15/07/2025		67797240	The chain links are worn excessively and require renewing	Replace worn chains	8	Maintenance	No Gra	855	Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park		No	1043730 Activity Equipment	Chain Traverse		No	15/07/2025		67797244	The connecting lugs are worn	Replace lugs or all affected components	8	Maintenance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park		No	1043718 Activity Equipment	Cross Chain Walk		No	15/07/2025		67797253	The connecting lugs are worn	Replace lugs or all affected components	8	Maintenance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park 3054 Swanscombe Park			1043710 Activity Equipment 1043710 Activity Equipment	Multi Play (Toddler) Multi Play (Toddler)		No No	15/07/2025 15/07/2025			There is moderate damage to the surface	Repair the damaged areas of surfacing	8	Maintenance	No We		Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park			1043717 Activity Equipment	Spring Balance Beam							Replace all affected timbers	8	Maintenance	No We		Playdale Playgrounds Ltd	Yes	
							15/07/2025			The surfacing dimensions are short and do not meet with the requirements of the current applicable standard		8	Compliance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park 3054 Swanscombe Park			1043717 Activity Equipment	Spring Balance Beam			15/07/2025			There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra		Playdale Playgrounds Ltd	Yes	
JWansconne Park		No	1043719 Activity Equipment	Stepping Posts Timber		No	15/07/2025		6//97230	There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
3054 Swanscombe Park		No	1043726 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797249	There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	ass	Playdale Playgrounds Ltd	Yes	Yes
8054 Swanscombe Park		No	1043725 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797262	There is algae or moss on the surface of the equipment	Clean and treat appropriately	8	Maintenance	No Gra	955	Playdale Playgrounds Ltd	Yes	Yes



Site Name	Site Site Item ID Item Reference Archived	Type Item	Part Number	Item Archived	Inspection Date	Life Expectancy	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer	Findin Photo
Swanscombe Park Swanscombe Park	No 1458818 Anci No 1458818 Anci		V = 1 P.		15/07/2025 15/07/2025			Repair perimeter of surfacing to remove trip points Replace all affected timber	8	Maintenance Maintenance	No N/A No N/A	Owner/Operator Owner/Operator	<u>Yes</u> <u>Yes</u>
Community Code	No 1043728 Gate	es Gate - Self Closing		No	15/07/2025		67797182 The gate is closing too quickly (less than 4 seconds)	Take corrective action to ensure that the gate closes in 4-8 seconds from 90	8	Maintenance	No Paving Slabs	Unknown	Yes
Swanscombe Park Swanscombe Park	No 1043728 Gate	es Gate - Self Closing		No	15/07/2025		67797180 There is moderate damage to the surface creating trip hazards	Repair the damaged areas of surfacing	8	Maintenance	No Paving Slabs	Unknown	Yes
Swanscombe Park	No 1043711 Othe	er Free Standing Slide		No	15/07/2025		67797222 There are projecting bolt thread(s) present	Remove excess thread length and deburr or provide cap	8	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes
Swanscombe Park	No 1043724 Swin	ngs 1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No	15/07/2025		67797192 The bush / bushes is / are worn or missing	Replace worn or missing bushes	8	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes
Swanscombe Park	No 1043720 Swin	ngs 2 Bay 4 Seat (Flat)	2.4m Traditional Swir		15/07/2025			Replace all corroded fixings	8	Maintenance	No Wet Pour	Wicksteed Playgrounds	No
Swanscombe Park Swanscombe Park	No 1043720 Swir No 1043720 Swir		2.4m Traditional Swir 2.4m Traditional Swir		15/07/2025 15/07/2025			Replace worn chains Repair the damaged areas of surfacing	8	Maintenance Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	No Yes
2Mauscounse Lark	110 20-3720 3111	53 Zody vocat (voty	2										
Valley View Play Area Valley View Play Area	No 1043773 Activ No 1458822 Anci		Discovery Multi-play	l No No	16/07/2025 16/07/2025			Monitor - No action given the risk assessment Remove trip hazard	8	Compliance Maintenance	No Wet Pour No N/A	Wicksteed Playgrounds Owner/Operator	Yes Yes
Valley View Play Area  Valley View Play Area	No 1458822 Anci			No	16/07/2025			Secure / Replace as required	8	Maintenance	No N/A	Owner/Operator	Yes
Valley View Play Area	No 1043782 Anci	illary Items Steps		No	16/07/2025		67797517 There is moderate damage to the surface	Repair the damaged areas of surfacing	8	Maintenance	No Concrete	Not Applicable	Yes
Valley View Play Area	No 1043770 Fend	ces Fencing - Flat Top		No	16/07/2025		67797494 The area between the fence has eroded leaving uneven areas, or the concrete foundations exposed, resulting in trip hazards at the entrance/exit	Reinstate to level with surrounding surfaces	8	Maintenance	No Grass	Unknown	Yes
Valley View Play Area	No 1043780 Rote	or Play Roundabout	Honeycomb Whirl	No	16/07/2025		to the playground 67797512 The surfacing dimensions are short and do not meet with the requirements	Monitor - No action given the risk assessment	8	Compliance	No Wet Pour	Wicksteed Playgrounds	Yes
							of the current applicable standard						
Broomfield Recreation Ground	No 1043685 Acti	ivity Equipment Multi Play (Junior)		No	15/07/2025		67797144 There is some minor damage to the surface	Monitor for any further deterioration and repair as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes
Broomfield Recreation Ground	No 1043685 Acti	ivity Equipment Multi Play (Junior)		No	15/07/2025		67797140 The ropes/nets are worn/damaged in places	Monitor for any further deterioration and repair or replace as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes
Broomfield Recreation Ground	No 1043685 Acti	ivity Equipment Multi Play (Junior)		No	15/07/2025		67797141 The perspex dome has been damaged	Replace	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Ye
Broomfield Recreation Ground	No 1043685 Acti	ivity Equipment Multi Play (Junior)		No	15/07/2025		67797142 The paintwork on this item has been damaged or worn exposing the metal	Treat affected areas and repaint	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Ye
Distribution of said							underneath which is rusting / corroding						
Broomfield Recreation Ground	No 1043703 Acti			No No	15/07/2025 15/07/2025			Replace missing or damaged bolt cap covers  Monitor for any further deterioration and replace when 40% worn	6	Maintenance Maintenance	No Grass No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	<u>Ye</u> Ye
Broomfield Recreation Ground Broomfield Recreation Ground	No 1043704 Acti No 1043704 Acti			No	15/07/2025		67797087 The item is slightly loose in its foundations	Monitor for any further deterioration and repair as required	6	Maintenance	No Grass Matrix Tiles	Playdale Playgrounds Ltd	<u>Y</u>
Broomfield Recreation Ground Broomfield Recreation Ground	No 1043699 And No 1043699 And			No No	15/07/2025 15/07/2025			Monitor for any further deterioration and repair as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Glasdon Glasdon	<u>Y</u> <u>Y</u>
Broomfield Recreation Ground	No 1043694 And	illary Items Sign	Outdoor Fitness Sign	n No	15/07/2025		67797156 There are projecting bolt thread(s) present	Remove excess thread length and deburr or provide cap	6	Maintenance	No Grass	Not Identified	7
Broomfield Recreation Ground	No 1458817 And	cillary Items Site General		No	15/07/2025		67797112 There is litter/debris in the area	Remove litter/debris from the area and maintain	6	Vandalism	No N/A	Owner/Operator	<u>Y</u>
Broomfield Recreation Ground Broomfield Recreation Ground Broomfield Recreation Ground	No 1043705 Fen No 1043691 Gat No 1043691 Gat	tes Gate - Self Closing		No No No	15/07/2025 15/07/2025 15/07/2025		67797094 The paint is flaking off the metalwork	Monitor for any further deterioration and repair as required Rub down and re-paint Monitor for any further deterioration and repair as required	6 6 6	Maintenance Maintenance Maintenance	No Grass No Paving Slabs No Paving Slabs	Unknown Unknown Unknown	<u>Ye</u> <u>Ye</u> <u>Ye</u>
Broomfield Recreation Ground Broomfield Recreation Ground		tdoor Fitness Equipment Air Walker tdoor Fitness Equipment Chest Press		No No	15/07/2025 15/07/2025		67797148 There is surface corrosion / rust present on the item 67797151 The surface has eroded in some areas and may be slippery in wet conditions	Consider treating the item s Reinstate the surface	6 6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo Caloo	1
Broomfield Recreation Ground		tdoor Fitness Equipment Chest Press		No	15/07/2025		67797152 There is surface corrosion / rust present on the item	Consider treating the item	6	Maintenance	No Grass Matrix Tiles	Caloo	
Broomfield Recreation Ground		tdoor Fitness Equipment Cross Rider tdoor Fitness Equipment Shoulder Press		No No	15/07/2025 15/07/2025		67797160 The paintwork on this item has been damaged or worn exposing the metal 67797154 The surface has eroded in some areas and may be slippery in wet conditions		6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo Caloo	
Broomfield Recreation Ground Broomfield Recreation Ground		tdoor Fitness Equipment Shoulder Press tdoor Fitness Equipment Shoulder Press		No	15/07/2025		67797155 The paintwork on this item has been damaged or worn exposing the metal	Treat affected areas and repaint	6	Maintenance	No Grass Matrix Tiles	Caloo	
Broomfield Recreation Ground	No 1043690 Ou	tdoor Fitness Equipment Skier		No	15/07/2025			Monitor for any further deterioration and replace as required	6	Maintenance	No Grass Matrix Tiles	Caloo	
	No 1043690 Out	tdoor Fitness Equipment Skier cking Equipment Four Way Springer		No No	15/07/2025 15/07/2025		67797159 The paintwork on this item has been damaged or worn exposing the metal 67797131 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding		6 6	Maintenance Maintenance	No Grass Matrix Tiles No Wet Pour	Caloo Playdale Playgrounds Ltd	
												Playdale Playgrounds Ltd	
Broomfield Recreation Ground	No 1043692 Roo	king Equipment Four Way Springer		No	15/07/2025		67797132 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour		
Broomfield Recreation Ground  Broomfield Recreation Ground	No 1043692 Roc	cking Equipment Four Way Springer					67797132 The item has been damaged	Monitor for any further deterioration and replace as required	6				
Broomfield Recreation Ground  Broomfield Recreation Ground  Broomfield Recreation Ground	No 1043692 Roc No 1043692 Roc No 1043692 Roc	cking Equipment Four Way Springer cking Equipment Four Way Springer cking Equipment Four Way Springer		No	15/07/2025 15/07/2025 15/07/2025				6 6 6	Maintenance Maintenance Vandalism	No Wet Pour No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	
Broomfield Recreation Ground  Broomfield Recreation Ground  Broomfield Recreation Ground  Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043692 Roc	cking Equipment Four Way Springer cking Equipment Four Way Springer	Glow worm	No	15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal	Treat any rusting components and repaint	6 6 6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
Broomfield Recreation Ground  Broomfield Recreation Ground  Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043700 Rot	cking Equipment Four Way Springer Cking Equipment Four Way Springer Cking Equipment See Saw tor Play Overhead Rotator		No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797197 There is/are bolt cap covers missing or damaged on the item 67797075 The bearing is showing signs of wear	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required	6 6 6	Maintenance Vandalism Maintenance Maintenance	No Wet Pour  No Wet Pour  No Wet Pour  No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043693 Roc  No 1043700 Roc  No 1043695 Sw	cking Equipment Four Way Springer Cking Equipment Four Way Springer Cking Equipment See Saw tor Play Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle	) 2.8m Traditional Sw	No No No No in No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797197 The bearing is showing signs of wear 67797007 The bearing is showing signs of wear 67797107 The sead is 15 are too close to the frame as defined in BS EN 1176 Part 2	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment	6 6 6 6	Maintenance Vandalism Maintenance Maintenance Compliance	No Wet Pour No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw  No 1043687 Sw  No 1043687 Sw	cking Equipment Four Way Springer Four Way Springer Four Way Springer  Cking Equipment See Saw  tor Play Overhead Rotator ings 2 Bay (2 Flat, 2 Cradle ings 2 Bay (2 Flat, 2 Cradle ings 2 Bay (2 Flat, 2 Cradle	) 2.8m Traditional Swi ) 2.8m Traditional Swi ) 2.8m Traditional Swi	No No No No in No in No in No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged  67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item  67797119 There is/are bolt cap covers missing or damaged on the item 677970705 The bearing is showing signs of wear 67797100 The seat's is/ are too close to the frame as defined in BS EN 1176 Part 2 67797110 The seats are too close to each other as defined in BS EN 1176 Part 2; this is	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment  Monitor - No arting further deterioration and replace when 40% worn	6 6 6 6 6	Maintenance Vandalism Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour  No Wet Pour  No Grass Matrix Tiles  No Wet Pour  No Wet Pour  No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw  No 1043687 Sw  No 1043687 Sw  No 1043687 Sw	cking Equipment Four Way Springer Four Way Springer  cking Equipment See Saw  tor Play Overhead Rotator ings 2 Bay (2 Flat, 2 Cradle ings 2 Bay (2 Flat, 2 Cradle ings 2 Bay (2 Flat, 2 Cradle	) 2.8m Traditional Sw ) 2.8m Traditional Sw ) 2.8m Traditional Sw ) 2.8m Traditional Sw	No No No in No in No in No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 6779719 There is/are boilt cap covers missing or damaged on the item 67797107 The bearing is showing signs of wear 67797109 The seat's is / are too close to ach other as defined in BS EN 1176 Part 2; this is 67797107 There is some wear to the shackles. 67797107 There is some wear to the shackles.	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn	6 6 6 6 6 6	Maintenance Vandalism Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour  No Wet Pour  No Wet Pour  No Grass Matrix Tiles  No Wet Pour  No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw	cking Equipment Cking Equipment Four Way Springer Four Way Springer Four Way Springer  Cking Equipment See Saw Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle Ings 2 Bay (2 Flat, 2 Cradle Ings 2 Bay (2 Flat, 2 Cradle 2 Bay (2 Flat, 2 Cradle 2 Bay (2 Flat, 2 Cradle 3 Bay (2 Flat, 2 Cradle 3 Bay (2 Flat, 2 Cradle	2.8m Traditional Sw	No No No in No in No in No in No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797139 The self self self self self self self sel	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment 5 Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn Rub down and re-paint	6 6 6 6 6 6	Maintenance Vandalism Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour  No Wet Pour  No Grass Matrix Tiles  No Wet Pour  No Wet Pour  No Wet Pour  No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw	cking Equipment See Saw Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle Ings 3 Bay (2 Flat, 2 Cradle Ings 4 Bay (2 Flat, 2 Cradle Ings 5 Bay (2 Flat, 2 Cr	2.8m Traditional Sw	No No No in No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is/are bolt cap covers missing or damaged on the item 67797107 The bearing is showing signs of wear 67797100 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some wear to the shackles. 67797100 The paint is flaking off the metalwork 67797101 The seath as minor damage or wear 67797001 The some notable evidence of chain wear	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment S Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn Rub down and re-paint  Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace when 40% worn	6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw	cking Equipment Four Way Springer Four Way Springer Four Way Springer  cking Equipment  See Saw Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle Ings 3 Bay (2 Flat, 2 Cradle Ings 3 Surf Swing Ings 5 Surf Swing Surf Swing	2.8m Traditional Sw	No No No in No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is some evidence of fire damage to the item 67797107 The bearing is showing signs of wear 67797107 The seat's is Jave too close to the frame as defined in BS EN 1176 Part 2 67797100 There is some wear to the shackles. 67797100 There is some wear to the shackles. 67797101 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some notable evidence of chain wear 67797101 The seat has minor damage or wear 67797102 There is some notable evidence of chain wear 6779707 There is some wear to the shackles. 67797556 There is some strimmer / machinery damage apparent on the posts, this	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required Monitor - No action given the risk assessment s Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn Rub down and re-paint  Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace when 40% worn	6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance Maintenance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Ltd Playdale Playgrounds Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd A.E.Evans	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw  No 1043682 Sw  No 1043682 Sw  No 1043682 Sw	cking Equipment Four Way Springer Four Way Springer Four Way Springer  cking Equipment  See Saw Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle Ings 3 Bay (2 Flat, 2 Cradle Ings 3 Surf Swing Ings 5 Surf Swing Surf Swing	2.8m Traditional Sw	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is/are bolt cap covers missing or damaged on the item 67797107 The bearing is showing signs of wear 67797100 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some wear to the shackles. 67797101 The paint is flaking off the metalwork 67797101 The seat has minor damage or wear 67797031 There is some notable evidence of chain wear 67797075 There is some wear to the shackles. 67797055 There is some strimmer / machinery damage apparent on the posts, this 67797555 There is some strimmer / machinery damage apparent on the posts, this	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Rub down and re-paint  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any deterioration (rot) and replace as required  Monitor for any further deterioration and replace as required	6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles No Grass Matrix Tiles No Grass Matrix Tiles No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Licksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Alexans Alexans Alexans	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw	cking Equipment cking Equipment cking Equipment cking Equipment cking Equipment  See Saw Overhead Rotator rings 2 Bay (2 Flat, 2 Cradle rings 3 Bay (2 Flat, 2 Cradle rings 5 Surf Swing rings 5 Surf Swing rings 5 Surf Swing rivity Equipment 8 Bridge rivity Equipment 8 Bridge rivity Equipment 8 Bridge	2.8m Traditional Sw	No No No in No in No in No in No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is some evidence of fire damage to the item 67797107 The bearing is showing signs of wear 67797107 The seat's is Jave too close to the frame as defined in BS EN 1176 Part 2 67797100 There is some wear to the shackles. 67797100 There is some wear to the shackles. 67797101 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some notable evidence of chain wear 67797101 The seat has minor damage or wear 67797102 There is some notable evidence of chain wear 6779707 There is some wear to the shackles. 67797556 There is some strimmer / machinery damage apparent on the posts, this	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor for any deterioration (rot) and replace as required  Monitor for any further deterioration and repair or replace as required	6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Ltd Playdale Playgrounds Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd A.E.Evans	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043693 Roc  No 1043687 Sw  No 1043682 Sw  No 1043683 Sw  No 1043683 Sw  No 1043684 Sw  No 1043685 Sw  No 1043685 Sw  No 1043686 Sw  No 1043686 Sw  No 1043796 Act  No 1043797 Act  No 1043796 Act  No 1043797 Act  No 104379 Act  No 10437	cking Equipment cking Equipment Four Way Springer See Saw Overhead Rotator Ings 2 Bay (2 Flat, 2 Cradle Ings 3 Bay (2 Flat, 2 Cradle Ings 5 Surf Swing Ings Surf Swing Surf Swing Four Bridge Fridge Fridge Fridge Fridge Fridge	2.8m Traditional Sw	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025 16/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is some evidence of fire damage to the item 67797107 The bearing is showing signs of wear 67797107 The seat's is 7 are too close to the frame as defined in BS EN 1176 Part 2 67797110 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some wear to the shackles. 67797101 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some mear to the shackles. 67797101 There is some notable evidence of chain wear 67797102 There is some notable evidence of chain wear 67797031 There is some wear to the shackles. 67797555 There is some strimmer / machinery damage apparent on the posts, this 67797555 The ropes/nets are worn/damaged in places 67797558 The timber has a number of splits/shakes or air cracks and this may affect 67797558 The timber has a number of splits/shakes or air cracks and this may affect 67797558 The timber has a number of splits/shakes or air cracks and this may affect 67797558 The timber strimmer / machinery damage apparent on the posts, this 67797558 The timber strimmer / machinery damage apparent on the posts, this 67797558 The splits/shakes or air cracks and this may affect 67797558 The splits/shakes or air cracks and this may affect 67797558 The splits/shakes or air cracks and this may affect 67797558 The splits/shakes or air cracks and this may affect 67797558 The splits/shakes or air cracks and this may affect 67797559 The splits/shakes or air cracks and this may affect 67797559 The splits/shakes or air cracks and this may affect 67797559 The splits/shakes or air cracks and this may affect 67797559 The splits/shakes or air cracks and this may affect	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor for any deterioration (rot) and replace as required  Monitor for any further deterioration and repair or replace as required	6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles No Grass Matrix Tiles No Grass Matrix Tiles No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Ltd Playdale Playgrounds Playdale Playgrounds Ltd Playdale Playgrounds Ltd A.E.Evans A.E.Evans	
Broomfield Recreation Ground	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043693 Roc  No 1043687 Sw  No 1043682 Sw  No 1043683 Sw  No 1043683 Sw  No 1043684 Sw  No 1043685 Sw  No 1043685 Sw  No 1043686 Sw  No 1043686 Sw  No 1043796 Act  No 1043797 Act  No 1043796 Act  No 1043797 Act  No 104379 Act  No 10437	cking Equipment Four Way Springer Cking Equipment See Saw Overhead Rotator Overhead Rotator 19 Bay (2 Flat, 2 Cradle 19 Bay	2.8m Traditional Sw	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is some evidence of fire damage to the item 67797107 The bearing is showing signs of wear 67797100 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some wear to the shackles. 67797101 The paint is flaking off the metalwork 67797101 The seat has minor damage or wear 6779702 There is some wear to the shackles. 67797035 There is some wear to the shackles. 67797055 There is some strimmer / machinery damage apparent on the posts, this 67797555 The mopes/nets are worn/damaged in places 67797556 The timber has a number of splits/shakes or air cracks and this may affect 67797546 The timber has a number of splits/shakes or air cracks and this may affect 67797546 The imber has a number of splits/shakes or air cracks and this may affect 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797550 There is some strimmer / machinery damage apparent on the posts, this 67797550 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797550 There is some strimmer / machinery damage apparent on the posts, this	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Rub down and re-paint  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor to ensure the splits do not cross through fixing points of the  Monitor to ensure the splits do not cross through fixing points of the	6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Licksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans	
Broomfield Recreation Ground Eagles Road Play Area	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043693 Roc  No 1043687 Sw  No 1043682 Sw  No 1043682 Sw  No 1043682 Sw  No 1043795 Act  No 1043796 Act  No 1043791 Act  No 1043791 Act	cking Equipment cking Equipment Four Way Springer Four Way Springer Four Way Springer  Cking Equipment Cking Equipment Four Way Springer  Cking Equipment Ckin	2.8m Traditional Sw 2.8m Traditional Sw 2.8m Traditional Sw 2.8m Traditional Sw 3.8m Traditional Sw 3.8m Traditional Sw 4.8m Traditional Sw	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797137 There is/are bolt cap covers missing or damaged on the item 67797107 The bearing is showing signs of wear 67797107 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 6779710 The seats are too close to each other as defined in BS EN 1176 Part 2; this is 6779710 There is some wear to the shackles. 6779710 The paint is flaking off the metalwork 67797101 The seat has minor damage or wear 67797073 There is some wear to the shackles. 67797556 There is some wear to the shackles. 67797557 There is some strimmer / machinery damage apparent on the posts, this 67797558 The timber has a number of splits/shakes or air cracks and this may affect 67797540 The timber has a number of splits/shakes or air cracks and this may affect 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Rub down and re-paint  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor to ensure the splits do not cross through fixing points of the  Monitor for any deterioration (rot) and replace as required  Monitor for any deterioration (rot) and replace as required	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Licksteed Playgrounds Playdale Playgrounds Playdale Playgrounds Ltd Playdale Playgrounds Ltd A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
Broomfield Recreation Ground Eagles Road Play Area Eagles Road Play Area	No 1043692 Roc  No 1043692 Roc  No 1043692 Roc  No 1043693 Roc  No 1043683 Roc  No 1043687 Sw  No 1043791 Act  No 1043791 Act  No 1043793 Act	cking Equipment Four Way Springer Cking Equipment See Saw Overhead Rotator Overhead Rotator 19 Bay (2 Flat, 2 Cradle 19 Bay	2.8m Traditional Sw 3.8m Traditional Sw 2.8m Traditional Sw	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025 16/07/2025		67797132 The item has been damaged 67797133 The paintwork on the spring has been damaged or worn exposing the metal 67797134 There is some evidence of fire damage to the item 67797175 There is some evidence of fire damage to the item 67797170 The seat's is / are too close to the frame as defined in BS EN 1176 Part 2 67797100 The seat's are too close to each other as defined in BS EN 1176 Part 2; this is 67797100 There is some wear to the shackles. 67797100 The paint is flaking off the metalwork 67797101 The seat sam of the metalwork 67797101 The seat's own entable evidence of chain wear 67797102 There is some notable evidence of chain wear 67797103 There is some notable evidence of chain wear 67797105 There is some wear to the shackles. 6779755 There is some strimmer / machinery damage apparent on the posts, this 6779755 The timber has a number of splits/shakes or air cracks and this may affect 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 There is some strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The strimmer / machinery damage apparent on the posts, this 67797540 The timber has a premerate the preservative applied to the timber and accelerate the 67797540 The timber has premerate the preservative applied to the timber and accelerate the	Treat any rusting components and repaint Monitor for any further deterioration and repair as required  Replace missing or damaged bolt cap covers Monitor for any further deterioration and replace as required  Monitor - No action given the risk assessment  Monitor - No action given the risk assessment  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Rub down and re-paint  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace when 40% worn  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Monitor to ensure the splits do not cross through fixing points of the  Monitor for any deterioration (rot) and replace as required  Monitor for any deterioration (rot) and replace as required	6 6 6 6 6 6 6 6	Maintenance Vandalism  Maintenance Maintenance Compliance Compliance Maintenance	No Wet Pour No Wet Pour No Grass Matrix Tiles No Wet Pour No Grass Matrix Tiles	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Wicksteed Playgrounds Playdale Playgrounds Ltd Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Wicksteed Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd A.E.Evans A.E.Evans A.E.Evans A.E.Evans A.E.Evans	7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7. 7



Site Name	Site Referen		d Item ID Item Type	Item	Part Number	Item Archived	Inspection Date	Life Expectancy	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer	F
Eagles Road Play Area		No	1043803 Activity Equipment	Rope Bridge	<del>2</del>	No	16/07/2025		67797533 There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
Eagles Road Play Area Eagles Road Play Area		No No	1043803 Activity Equipment 1043806 Activity Equipment	Rope Bridge Rope Tunnel			16/07/2025 16/07/2025		rotting process The timber has a number of splits/shakes or air cracks and this may affect 67797534 There is some strimmer / machinery damage apparent on the posts, this		6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	A.E.Evans A.E.Evans	
									can penetrate the preservative applied to the timber and accelerate the			Municipalice	110 51032 11101111 11103		
Eagles Road Play Area Eagles Road Play Area		No No	1043806 Activity Equipment 1043787 Activity Equipment	Rope Tunnel Rope Walk			16/07/2025		67797538 The timber has a number of splits/shakes or air cracks and this may affect		6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
Eagles Road Play Area		No	1043787 Activity Equipment	Rope Walk			16/07/2025 16/07/2025		67797527 There is some strimmer / machinery damage apparent on the posts, this 67797528 The timber has a number of splits/shakes or air cracks and this may affect		6	Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	A.E.Evans A.E.Evans	
Eagles Road Play Area		No	1043795 Activity Equipment	Rotating Beam			16/07/2025		67797526 A number of fixing(s) have worked loose	Secure all loose fixings	6	Maintenance Maintenance	No Grass Matrix Tiles	A.E.Evans	
gles Road Play Area		No	1043795 Activity Equipment	Rotating Beam		No	16/07/2025		67797523 There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
egles Road Play Area		No	1043792 Activity Equipment	Spring Balance Beam			16/07/2025		67797555 The paintwork on this item has been damaged or worn exposing the metal		6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
gles Road Play Area gles Road Play Area		No No	1043808 Activity Equipment 1043790 Activity Equipment	Stepping Posts Timber Stilts			16/07/2025 16/07/2025		67797542 There is some strimmer / machinery damage apparent on the posts, this 67797535 There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required Monitor for any deterioration (rot) and replace as required	6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	A.E.Evans A.E.Evans	
									can penetrate the preservative applied to the timber and accelerate the			THO ME HOLD			
gles Road Play Area gles Road Play Area		No No	1043790 Activity Equipment 1043801 Activity Equipment	Stilts Traverse Ropes	Traversing Nets & Wa		16/07/2025 16/07/2025		67797536 The timber has a number of splits/shakes or air cracks and this may affect	Monitor to ensure the splits do not cross through fixing points of the	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
les Road Play Area		No	1043801 Activity Equipment	Traverse Ropes	Traversing Nets & Wa		16/07/2025		67797561 The timber has a number of splits/shakes or air cracks and this may affect 67797562 A number of fixing(s) have worked loose	Monitor to ensure the splits do not cross through fixing points of the Secure all loose fixings	6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	A.E.Evans A.E.Evans	
les Road Play Area		No	1043801 Activity Equipment	Traverse Ropes	Traversing Nets & Wa	No	16/07/2025		67797563 There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
les Road Play Area les Road Play Area		No No	1043801 Activity Equipment 1043798 Ancillary Items	Traverse Ropes Bench	Traversing Nets & Wa		16/07/2025 16/07/2025			Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
les Road Play Area		No	1043807 Fences	Fencing - Timber			16/07/2025			Monitor for any deterioration (rot) and replace as required Monitor for any deterioration (rot) and replace as required	6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	
les Road Play Area		No	1043794 Gates	Gate - Combination			16/07/2025		67797530 There is no padlock on the maintenance gate	Provide a padlock to secure the gate	6	Maintenance	No Mixed Surface	Unknown	
gles Road Play Area		No	1043805 Signs	Playground Sign		No	16/07/2025		67797570 The adjacent foliage is overhanging	Cut back and maintain	6	Maintenance	No N/A	Not Applicable	
gles Road Play Area		No	1043802 Swings	Basket Swing - Type 1	2.3m Timber Swing	No	16/07/2025		67797554 The seat has minor damage or wear	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
les Road Play Area		No	1043802 Swings	Basket Swing - Type 1	2.3m Timber Swing	No	16/07/2025		67797551 There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
les Road Play Area		No	1043802 Swings	Basket Swing - Type 1	2.3m Timber Swing		16/07/2025		67797552 There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass Matrix Tiles	A.E.Evans	
ritage Park ritage Park		No No	1186749 Activity Equipment 1186763 Ancillary Items	Activity Trail Picnic Table			15/07/2025 15/07/2025		67797175 The item is slightly loose in its foundations 67797167 The paintwork on this item has been damaged or worn exposing the metal	Monitor for any further deterioration and repair as required	6	Maintenance Maintenance	No Grass No Concrete	Playdale Playgrounds Ltd Unknown	
ritage Park		No	1186761 Fences	Fence - Bow Top			15/07/2025		underneath which is rusting / corroding 67797172 There is some damage to the fence sections	Monitor for any further deterioration and repair as required	6	Maintenance	No Grass	Unknown	
tage Park		No	1186761 Fences	Fence - Bow Top			15/07/2025		67797165 Cable ties are present and there are sharp projecting ends	Remove	6	Installation	No Grass	Unknown	
tage Park		No	1186760 Gates	Gate - Combination		No	15/07/2025		67797170 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Treat affected areas and repaint	6	Maintenance	No Mixed Surface	Unknown	
age Park		No	1186760 Gates	Gate - Combination		No	15/07/2025		67797171 Cable ties are present and there are sharp projecting ends	Remove	6	Installation	No Mixed Surface	Unknown	
tage Park		No	1186740 Gates	Gate - Self Closing		No	15/07/2025		67797162 Cable ties are present and there are sharp projecting ends	Remove	6	Installation	No Mixed Surface	Unknown	
khall Recreation Ground khall Recreation Ground		No No	1043759 Activity Equipment 1043759 Activity Equipment	Multi Play (Senior) Multi Play (Senior)			15/07/2025 15/07/2025		67797469 The ropes/nets are worn/damaged in places 67797470 The rope connectors are showing signs of corrosion	Monitor for any further deterioration and repair or replace as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	
														,	
khall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797460 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
khall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797465 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Treat affected areas and repaint	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
ckhall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797466 A number of fixing(s) have worked loose	Secure all loose fixings	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
ckhall Recreation Ground		No	1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797463 There are gaps opening between the surfacing and the edging surround or between the joints in the surfacing	Monitor for any further deterioration and repair as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
ckhall Recreation Ground		No	1043752 Activity Equipment	Multi Play (Toddler)			15/07/2025		67797443 The timber has a number of splits/shakes or air cracks and this may affect		6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
ockhall Recreation Ground ockhall Recreation Ground		No No	1043752 Activity Equipment 1043752 Activity Equipment	Multi Play (Toddler) Multi Play (Toddler)			15/07/2025 15/07/2025		67797444 There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
ckhall Recreation Ground		No	1043752 Activity Equipment	Multi Play (Toddler)			15/07/2025		67797441 There are gaps opening between the surfacing and the edging surround or 67797446 A number of fixing(s) have worked loose	Monitor for any further deterioration and repair as required Secure all loose fixings	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	
alstall December Council		No	1042761 Assillanda	Line Bio			45 (07 (000								
ckhall Recreation Ground ckhall Recreation Ground		No	1043761 Ancillary Items 1043761 Ancillary Items	Litter Bin Litter Bin			15/07/2025 15/07/2025		67797484 The paintwork on this item has been damaged or worn exposing the metal 67797436 The item is slightly loose in its foundations	Treat affected areas and repaint  Monitor for any further deterioration and repair as required	6 6	Maintenance Maintenance	No Grass	Glasdon Glasdon	
ckhall Recreation Ground		No	1043749 Ancillary Items	Sign	Outdoor Fitness Sign	No	15/07/2025		67707420						
ckhall Recreation Ground		No	1458821 Ancillary Items	Site General	Outdoor Fitness Sign		15/07/2025		67797430 A number of fixing(s) have worked loose 67797448 The surface has eroded in some areas and may be slippery in wet condition:	Secure all loose fixings as Reinstate the surface	6	Maintenance Maintenance	No Grass No N/A	Not Identified Owner/Operator	
khall Recreation Ground		No	1458821 Ancillary Items	Site General			15/07/2025		67797457 The safety surface around the area is beginning to wear	Monitor for any further deterioration and repair as required	6	Maintenance	No N/A	Owner/Operator	
khall Recreation Ground		No	1043760 Fences	Fence		No	15/07/2025		67797437 The paint is flaking off the metalwork	Rub down and re-paint	6	Maintenance	No Grass	Unknown	
khall Recreation Ground		No	1043760 Fences	Fence		No	15/07/2025		67797438 There is some damage to the fence sections	Monitor for any further deterioration and repair as required	6	Maintenance	No Grass	Unknown	
		No	1043765 Gates	Gate - Self Closing			15/07/2025		67797433 The paint is flaking off the metalwork	Rub down and re-paint	6	Maintenance	No Paving Slabs	Unknown	
		No	1043765 Gates 1043746 Gates	Gate - Self Closing			15/07/2025		67797434 Cable ties are present and there are sharp projecting ends	Remove	6	Installation	No Paving Slabs	Unknown	
khall Recreation Ground		NO	1043746 Gates	Kissing Gate		No	15/07/2025		67797485 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Treat affected areas and repaint	6	Maintenance	No Paving Slabs	Unknown	
khall Recreation Ground				Free Standing Slide			15/07/2025		67797477 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	
khall Recreation Ground khall Recreation Ground khall Recreation Ground			1043751 Other	Ale Mallins		No	15/07/2025		67797425 The paintwork on this item has been damaged or worn exposing the metal		6	Maintenance Maintenance	No Grass Matrix Tiles	Caloo Caloo	
khall Recreation Ground khall Recreation Ground khall Recreation Ground khall Recreation Ground		No No No	1043763 Outdoor Fitness Equipment	Air Walker Chest Press		No	15/07/2025					ivialntenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo Caloo	
khall Recreation Ground khall Recreation Ground khall Recreation Ground khall Recreation Ground khall Recreation Ground		No		Air Walker Chest Press Cross Rider			15/07/2025 15/07/2025		67797428 The paintwork on this item has been damaged or worn exposing the metal 67797427 The paintwork on this item has been damaged or worn exposing the metal		6	Maintenance			
khall Recreation Ground		No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment	Chest Press Cross Rider		No	15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Treat affected areas and repaint	6				
chall Recreation Ground		No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment	Chest Press		No No			67797427 The paintwork on this item has been damaged or worn exposing the metal	Treat affected areas and repaint	6	Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo Caloo	
khall Recreation Ground		No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043758 Outdoor Fitness Equipment	Chest Press Cross Rider Shoulder Press Skier		No No No	15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 6779742 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item	Treat affected areas and repaint Treat affected areas and repaint Consider treating the item	6 6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo	
khall Recreation Ground		No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment	Chest Press Cross Rider Shoulder Press	2.3m Swing	No No No	15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding from the paintwork on this item has been damaged or worn exposing the metal 67797426 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required	6 6	Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A	Caloo Not Identified	
chall Recreation Ground creation Ground creati		No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043765 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043747 Activity Equipment	Chest Press Cross Rider Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Umior)	2.3m Swing	No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797426 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings	6 6 6	Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles	Caloo	
khall Recreation Ground pr Park		No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043758 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings	Chest Press Cross Rider Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle)	2.3m Swing	No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797326 The timber has a number of splits/shakes or air cracks and this may affect	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the	6 6 6 6	Maintenance Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour	Caloo Not Identified Caloo	
khall Recreation Ground or Park		No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043765 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043747 Activity Equipment	Chest Press Cross Rider Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Umior)	2.3m Swing	No No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797426 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the	6 6 6 6 6	Maintenance Maintenance Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour No Wet Pour	Caloo Not Identified Caloo Setter Play	
khall Recreation Ground or Park or Park		No No No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043737 Activity Equipment 1043737 Activity Equipment	Chest Press Cross Rider Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior)	2.3m Swing	No No No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797326 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797319 A number of fixing(s) have worked loose on the rope connectors	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the  Structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings	6 6 6 6 6	Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour	Caloo  Not Identified Caloo Setter Play Setter Play Setter Play Setter Play	
chall Recreation Ground or Park or Park or Park		No No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043758 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043748 Swings 1043737 Activity Equipment	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior)	2.3m Swing	No No No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797318 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 A number of fixing(s) have worked loose on the rope connectors 67797312 A number of fixing(s) have worked loose on the rope connectors 67797312 Parts of the timber are rough or splintered	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the s structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all loose fixings  Remove all rough or sharp edges	6 6 6 6 6 6	Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour	Caloo  Not Identified Caloo Setter Play Setter Play Setter Play Setter Play Setter Play	
khall Recreation Ground chall Recreation Ground chall Recreation Ground creation Ground chall Recreation Ground creation Ground chall Recreation Ground creation Ground chall Recreation Ground chall		No No No No No No No No	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043737 Activity Equipment 1043737 Activity Equipment	Chest Press Cross Rider Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior)	2.3m Swing	No No No No No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797326 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797319 A number of fixing(s) have worked loose on the rope connectors	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the  Structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings	6 6 6 6 6 6 6 6	Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour	Caloo  Not Identified Caloo Setter Play Setter Play Setter Play Setter Play	
khall Recreation Ground chall Recreation Ground chall Recreation Ground or Park or Park or Park or Park or Park or Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043765 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043745 Ancillary Items	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Multi Play (Junior)  Multi Play (Junior) Multi Play (Junior) Multi Play (Junior) Multi Play (Junior) Multi Play (Junior) Multi Play (Junior) Multi Play (Junior) Site General	2.3m Swing	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 The paintwork on this item has been damaged or worn exposing the metal 67797435 The item has been damaged 67797436 The seat has minor damage or wear 67797326 A number of fixing(s) have worked loose 67797326 The timber has a number of splits/hakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797319 A number of fixing(s) have worked loose on the rope connectors 67797312 Parts of the timber are rough or splintered 67797317 There gave fixed are worn/damaged in places 67797337 There are gaps opening between the surfacing and the edging surround or	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required	6 6 6 6 6 6 6 6 6	Maintenance	No Grass Matrix Tiles No Grass Matrix Tiles No N/A No Wet Pour	Caloo  Not Identified Caloo Setter Play	
khall Recreation Ground chall Recreation Ground chall Recreation Ground cr Park or Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043767 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043768 Signs 1043748 Swings 1043748 Swings 1043737 Activity Equipment 1043745 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Litter Bin  Site General Site General	2.3m Swing	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797318 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 A number of fixing(s) have worked loose on the rope connectors 67797312 Parts of the timber are rough or splintered 67797314 The topes/nets are worn/damaged in places 67797317 The item is slightly loose in its foundations 67797317 There are gaps opening between the surfacing and the edging surround or 67797310 The surface has eroded in some areas and may be slippery in wet conditions	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the s structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  s Reinstate the surface	6 6 6 6 6 6 6	Maintenance	No Grass Matrix Tiles No M/A No Wet Pour No Grass No N/A No N/A	Caloo  Not Identified Caloo Setter Play Glasdon Owner/Operator Owner/Operator	
ckhall Recreation Ground or Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043765 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043745 Ancillary Items	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Litter Bin Site General Site General Site General	2.3m Swing	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797435 The item has been damaged or worn exposing the metal 67797345 The seat has minor damage or wear 67797326 The timehr has a number of spitis/fshakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797318 A number of fixing(s) have worked loose on the rope connectors 67797312 Parts of the timber are rough or splintered 67797314 The ropes/nets are worn/damaged in places 67797337 The item is slightly loose in its foundations 67797317 There are gaps opening between the surfacing and the edging surround or 67797305 The surface has eroded in some areas and may be slippery in wet condition 67797305 There is weed // vegetation growth within the surface	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required to the second of th	6 6 6 6 6 6 6 6 6	Maintenance	NO Grass Matrix Tiles NO Grass Matrix Tiles NO N/A NO Wet Pour NO Met Pour	Caloo  Not Identified Caloo Setter Play Glasdon Owner/Operator Owner/Operator	
ckhall Recreation Ground chall Recreation Ground cor Park tor Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043758 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043745 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Litter Bin  Site General Site General	2.3m Swing	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797435 The item has been damaged 67797454 The seat has minor damage or wear 67797325 A number of fixing(s) have worked loose 67797318 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 A number of fixing(s) have worked loose on the rope connectors 67797312 Parts of the timber are rough or splintered 67797314 The topes/nets are worn/damaged in places 67797317 The item is slightly loose in its foundations 67797317 There are gaps opening between the surfacing and the edging surround or 67797310 The surface has eroded in some areas and may be slippery in wet conditions	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the s structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  s Reinstate the surface	6 6 6 6 6 6 6 6 6 6	Maintenance	No Grass Matrix Tiles No M/A No Wet Pour No Grass No N/A No N/A	Caloo  Not Identified Caloo Setter Play Glasdon Owner/Operator Owner/Operator	
ckhall Recreation Ground chhall Recreation Ground cor Park tor Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043758 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043737 Activity Equipment 1043738 Activity Equipment 1043739 Activity Equipment 1043745 Ancillary Items 1458819 Fences	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Litter Bin  Site General Site General Site General Fence - Bow Top Fence - Bow Top	2.3m Swing	NO N	15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal There is surface corrosion / rust present on the item 67797426 The item has been damaged 67797454 The seat has minor damage or wear 67797327 A number of fixing(s) have worked loose 67797328 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797318 A number of fixing(s) have worked loose on the rope connectors 67797318 The item has been damaged 67797317 The ries word of the fixing of the stability or allow water ingress which will accelerate the rotting process 67797317 There are gaps opening between the surfacing and the edging surround or 67797300 The ries weed / vegetation growth within the surface 67797331 There is weed / vegetation growth within the surface 67797341 There is some damage to the fence sections 67797341 There are a number of loose posts around the fence	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the  structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  See instate the surface  Remove weed / vegetation growth  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required	6 6 6 6 6 6 6 6 6 6	Maintenance	No Grass Matrix Tiles No M/A No Wet Pour No Met Pour No Met Pour No Met Pour No Met Pour No Grass No N/A No N/A No N/A No Grass No Grass	Caloo  Not Identified Caloo Setter Play Glasdon Owner/Operator Owner/Operator Not Identified Not Identified	
ckhall Recreation Ground chall Recreatio		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043757 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043765 Signs 1043748 Swings 1043737 Activity Equipment 1043738 Activity Equipment 1043745 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items 1043740 Fences 1043740 Fences	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Site General Site General Site General Site General Fence - Bow Top Fence - Chainlink Gate - Maintenance	2.3m Swing	No N	15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal 67797426 There is surface corrosion / rust present on the item 67797426 The item has been damaged 67797427 The item has been damaged or wear 67797325 A number of fixing(s) have worked loose 67797326 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797319 A number of fixing(s) have worked loose on the rope connectors 67797314 The tropes/nets are worn/damaged in places 67797317 The item is slightly loose in its foundations 67797305 The item is slightly loose in its foundations 67797307 There is sweed damage to the fence sections 67797331 There is sweed amage to the fence sections 67797333 The item is some damage to the fence sections 67797333 The item is some damage to the fence sections 67797333 The item has been damaged	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the s structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all rough or sharp edges  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required	6 6 6 6 6 6 6 6 6 6	Maintenance	No Grass Matrix Tiles No M/A No N/A No Wet Pour No Grass No N/A No N/A No Grass	Caloo  Not Identified Caloo Setter Play Glasdon  Owner/Operator Owner/Operator Owner/Operator Not Identified	
khall Recreation Ground chall Recreation Ground chall Recreation Ground chall Recreation Ground or Park		NO N	1043763 Outdoor Fitness Equipment 1043769 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043747 Outdoor Fitness Equipment 1043766 Signs 1043748 Swings 1043747 Activity Equipment 1043737 Activity Equipment 1043745 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items 1458819 Ancillary Items 1043740 Fences 1043740 Fences	Chest Press Cross Rider  Shoulder Press Skier  Playground Sign 2 Bay (2 Flat, 2 Cradle) Multi Play (Junior) Litter Bin  Site General Site General Site General Fence - Bow Top Fence - Bow Top	2.3m Swing	No N	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797427 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding 67797429 The paintwork on this item has been damaged or worn exposing the metal There is surface corrosion / rust present on the item 67797426 The item has been damaged 67797435 The item has been damaged or worn exposing the metal 67797345 The seat has minor damage or wear 67797326 The timebr has a number of fishifs/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process 67797318 The item has been damaged 67797319 A number of fixing(s) have worked loose on the rope connectors 67797319 Parts of the timber are rough or splintered 67797317 There are gaps opening between the surfacing and the edging surround or 67797305 The surface has eroded in some areas and may be slippery in wet conditions 67797331 There is weed yeegation growth within the surface 67797341 There is some damage to the fence sections 67797341 There are a number of loose posts around the fence	Treat affected areas and repaint  Treat affected areas and repaint  Consider treating the item  Monitor for any further deterioration and replace as required  Monitor for any further deterioration and replace as required  Secure all loose fixings  Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability  Monitor for any further deterioration and replace as required  Secure all loose fixings  Remove all loose fixings  Monitor for any further deterioration and repair or replace as required  Monitor for any further deterioration and repair as required  Monitor for any further deterioration and repair as required to see the second of the second	6 6 6 6 6 6 6 6 6 6 6 6	Maintenance	NO Grass Matrix Tiles NO N/A NO N/A NO Wet Pour NO Met Pour NO Grass NO N/A NO N/A NO N/A NO Grass NO Grass	Caloo  Not Identified Caloo Setter Play Glasdon Owner/Operator Owner/Operator Not Identified Not Identified Unknown	



e ID Site Name	Site Referen	Site ce Archiv	tem ID Item Type	Item	Part Number	Item Archived	Inspection Date	Life Expectancy	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer	Finding Photo	
DSS Manor Park DSS Manor Park		No No		Gate - Self Closing Spring Motorbike			15/07/2025 15/07/2025				Rub down and re-paint Rub down and re-paint	6	Maintenance Maintenance	No Tarmac No Wet Pour	Not Identified Wicksteed Playgrounds	Yes Yes	
Manor Park		No		Roundabout	Honeycomb Whirl	No	15/07/2025				Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
Manor Park Manor Park		No No	•	Roundabout Roundabout	Honeycomb Whirl Honeycomb Whirl	No No	15/07/2025 15/07/2025			The paintwork on this item has been damaged or worn exposing the metal The item has been damaged	Treat affected areas and repaint  Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes	
Manor Park		No		Roundabout	Honeycomb Whirl	No	15/07/2025				Secure all loose fixings	6	Maintenance Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes Yes	
Manor Park		No		1 Bay 2 Seat (Flat)	2.1m Double Arch Swi		15/07/2025		67797311	The paintwork on this item has been damaged or worn exposing the metal		6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
Manor Park		No	1043734 Swings	1 Bay 2 Seat (Flat)	2.1m Double Arch Swi	No	15/07/2025			underneath which is rusting / corroding There is some wear to the shackles.	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	Ye
Manor Park Manor Park		No No		1 Bay 2 Seat (Flat)	2.1m Double Arch Swi 2.1m Double Arch Swi		15/07/2025				Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
		No.		1 Bay 2 Seat (Flat)	Inclined Balance Bean		15/07/2025 15/07/2025				Monitor for any further deterioration and replace when 40% worn  Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
Saxon Court Play Area Saxon Court Play Area		No		Balance Beam Balance Beam	inclined balance bean	No	15/07/2025			There is some strimmer / machinery damage apparent on the posts, this There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required  Monitor for any deterioration (rot) and replace as required	6 6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	Yes Yes	
Saxon Court Play Area		No	1043828 Activity Equipment	Balance Beam		No	15/07/2025		67797380	There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	
Saxon Court Play Area		No	1043829 Activity Equipment	Burma Bridge		No	15/07/2025			There is some strimmer / machinery damage apparent on the posts, this		6	Maintenance	No Grass	Unknown	No	Ye
Saxon Court Play Area		No	1043829 Activity Equipment	Burma Bridge		No	15/07/2025			The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process		6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		No		Burma Bridge		No	15/07/2025			There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		No		Multi Play (Junior)	Zigzag Tower & Slide	No	15/07/2025				Monitor for any further deterioration and repair as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
Saxon Court Play Area		No	1043823 Activity Equipment	Rope Traverse	Cross Rope Traverse		15/07/2025				Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area Saxon Court Play Area		No No		Rope Traverse	Parallel Rope Traverse		15/07/2025			There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	
Saxon Court Play Area Saxon Court Play Area		No No		Rope Traverse Rope Traverse	Parallel Rope Traverse Cross Rope Traverse	No No	15/07/2025 15/07/2025				Monitor to ensure the splits do not cross through fixing points of the Monitor for any deterioration (rot) and replace as required	6 6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	Yes Yes	
Saxon Court Play Area		No		Rope Traverse	Parallel Rope Traverse		15/07/2025		67797390	There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Unknown	Yes	
Saxon Court Play Area		No	o 1043822 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797388		Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area							-33.5			can penetrate the preservative applied to the timber and accelerate the rotting process							
Saxon Court Play Area		No No		Stepping Posts Timber Stepping Posts Timber		No No	15/07/2025 15/07/2025			There is some evidence of rot in the timber There is some strimmer / machinery damage apparent on the posts, this	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown Unknown	Yes	
Saxon Court Play Area Saxon Court Play Area		No.		Stepping Posts Timber Stepping Posts Timber		No	15/07/2025			There is some strimmer / machinery damage apparent on the posts, this There is some evidence of rot in the timber	Monitor for any deterioration (rot) and replace as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Unknown	Yes Yes	
Saxon Court Play Area		No	o 1043812 Activity Equipment	Stepping Posts Timber		No	15/07/2025		ar an la a	can penetrate the preservative applied to the timber and accelerate the	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		No	o 1043812 Activity Equipment	Stepping Posts Timber		No	15/07/2025			rotting process There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		No	o 1043815 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797381	There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		No	1043815 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797382	There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Unknown	Yes	<u>Y</u>
Saxon Court Play Area		No No		Toadstools Wobble Board		No No	15/07/2025 15/07/2025			The item has been damaged There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Island Leisure Unknown	Yes	
Saxon Court Play Area Saxon Court Play Area		No		Wobble Board		No	15/07/2025			The connecting lugs are showing signs of wear	Monitor for any further deterioration and replace as required  Monitor for any further deterioration and repair as required	6	Maintenance Maintenance	No Grass No Grass	Unknown	Yes Yes	
Saxon Court Play Area		No		Wobble Board		No	15/07/2025		67797375		Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Unknown	Yes	
Saxon Court Play Area		No	1458824 Ancillary Items	Site General		No	15/07/2025				Remove weed / vegetation growth	6	Maintenance	No N/A	Owner/Operator	Yes	Ye
Saxon Court Play Area		No	to the second se	Site General		No	15/07/2025			,	Cut back and maintain	6	Maintenance	No N/A	Owner/Operator	Yes	
Saxon Court Play Area Saxon Court Play Area		No No		Fence - Chainlink Fence - Chainlink		No No	15/07/2025 15/07/2025		67797415	There is some damage to the fence sections The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Monitor for any further deterioration and repair as required  Treat affected areas and repaint	6 6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	<u>Yes</u>	
		N	1043819 Fences	Fence - Steel Mesh		No	15/07/2025										
Saxon Court Play Area Saxon Court Play Area		No.		Fence - Steel Mesh		No	15/07/2025			There is some damage to the fence sections	Reinstate surrounding surfaces to cover the foundations  Monitor for any further deterioration and repair as required	6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	Yes Yes	
Saxon Court Play Area		N	1043819 Fences	Fence - Steel Mesh		No	15/07/2025		67797412	There are a number of fixings missing from the fence	Replace missing fixings	6	Maintenance	No Grass	Unknown	Yes	
Saxon Court Play Area		N	0 1043819 Fences	Fence - Steel Mesh		No	15/07/2025			The paintwork on this item has been damaged or worn exposing the metal	Treat affected areas and repaint	6	Maintenance	No Grass	Unknown	Yes	Ye
Saxon Court Play Area		N	o 1043817 Gates	Gate - Combination		No	15/07/2025			underneath which is rusting / corroding  The rubber buffer is missing from the latch plate	Replace rubber buffer	6	Maintenance	No Tarmac	Unknown	Yes	Ye
Saxon Court Play Area Saxon Court Play Area		N:		Gate - Combination Gate - Combination		No No	15/07/2025 15/07/2025			The paintwork on this item has been damaged or worn exposing the metal There is no padlock on the maintenance gate	Treat affected areas and repaint Provide a padlock to secure the gate	6	Maintenance Maintenance	No Tarmac No Tarmac	Unknown Unknown	Yes Yes	
Saxon Court Play Area		N		Gate - Self Closing			15/07/2025		67797396	The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding		6	Maintenance	No Tarmac	Unknown	Yes	
Saxon Court Play Area		N	o 1043825 Gates	Gate - Self Closing		No	15/07/2025			Cable ties are present and there are sharp projecting ends	Remove	6	Installation	No Tarmac	Unknown	Yes	Ye
Saxon Court Play Area		N		Gate - Self Closing		No	15/07/2025			The rubber buffer is missing from the latch plate	Replace rubber buffer	6	Maintenance	No Tarmac	Unknown	Yes	
O Saxon Court Play Area		N		Playground Sign		No	15/07/2025				Cut back and maintain	6	Maintenance	No N/A	Not Identified	Yes	Y
D Saxon Court Play Area		N	0 1043820 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.3m Swing	No	15/07/2025		67797358	There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Caloo	Yes	Y
4 Swanscombe Park 4 Swanscombe Park		N:		A Frame Climber Balance Beam	Inclined Balance Bean	No No	15/07/2025 15/07/2025			There are gaps opening between the surfacing and the edging surround or There is some strimmer / machinery damage apparent on the posts, this		6 6	Maintenance Maintenance	No Wet Pour No Grass	Wicksteed Playgrounds Playdale Playgrounds Ltd	Yes Yes	
										can penetrate the preservative applied to the timber and accelerate the rotting process							
Swanscombe Park		N		Balance Beam		No	15/07/2025		67797236	There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	
Swanscombe Park Swanscombe Park		N.		Balance Beam Balance Beam		No No	15/07/2025 15/07/2025			There is some evidence of rot in the timber The timber has a number of splits/shakes or air cracks and this may affect	Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	
Swanscombe Park		N		Balance Beam	Inclined Balance Bean		15/07/2025			There is some strimmer / machinery damage apparent on the posts, this		6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	
		N		Balance Beam	Inclined Balance Bean		15/07/2025		67797234	The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process	Monitor to ensure the splits do not cross through fixing points of the	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	
4 Swanscombe Park		N		Balance Beam	Inclined Balance Bean		15/07/2025			There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	
Swanscombe Park		N		Bridge Bridge		No No	15/07/2025 15/07/2025			There is some strimmer / machinery damage apparent on the posts, this The ropes/nets are worn/damaged in places	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	No	
Swanscombe Park Swanscombe Park		N	St. Contraction Interest St. Contraction C	Bridge Bridge		No No	15/07/2025			The ropes/nets are worn/damaged in places The rope connectors are showing signs of corrosion	Monitor for any further deterioration and repair or replace as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	No Yes	
Swanscombe Park Swanscombe Park Swanscombe Park				Bridge		No	15/07/2025		67797280	Parts of the timber are rough or splintered	Remove all rough or sharp edges	6	Maintenance	No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes	
Swanscombe Park Swanscombe Park Swanscombe Park Swanscombe Park		N	o 1043712 Activity Equipment									1900	000000000000000000000000000000000000000			Yes	
Swanscombe Park Swanscombe Park Swanscombe Park Swanscombe Park Swanscombe Park Swanscombe Park		N N	o 1043712 Activity Equipment	Bridge		No	15/07/2025			The timber has a number of splits/shakes or air cracks and this may affect		6	Maintenance	No Grass	Playdale Playgrounds Ltd		
Swanscombe Park		N N N	o 1043712 Activity Equipment o 1043727 Activity Equipment	Bridge Burma Bridge		No	15/07/2025		67797271	There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	1
Swanscombe Park		N N N	o 1043712 Activity Equipment o 1043727 Activity Equipment o 1043727 Activity Equipment	Bridge Burma Bridge Burma Bridge		No No	15/07/2025 15/07/2025		67797271 67797268	There is some evidence of rot in the timber There is some wear to the shackles.	Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace when 40% worn	6 6 6	Maintenance Maintenance	No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	Y
Swanscombe Park		N N N	1043712 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment	Bridge Burma Bridge		No	15/07/2025		67797271 67797268 67797269	There is some evidence of rot in the timber There is some wear to the shackles. The connecting lugs are showing signs of wear	Monitor for any further deterioration and replace as required	6 6 6 6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	Y: Y: Y:
Swanscombe Park		N N N N N N	o 1043712 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment	Bridge Burma Bridge Burma Bridge Burma Bridge Burma Bridge Burma Bridge		No No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797271 67797268 67797269 67797265 67797266	There is some evidence of rot in the timber There is some wear to the shackles. The connecting lugs are showing signs of wear There is some strimmer / machinery damage apparent on the posts, this The timber has a number of splits/shakes or air cracks and this may affect	Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and repair as required Monitor for any deterioration (rot) and replace as required Monitor to ensure the splits do not cross through fixing points of the	6 6 6 6	Maintenance Maintenance Maintenance Maintenance Maintenance	No Grass No Grass No Grass No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes Yes No Yes	Y: Y
Swanscombe Park		N N N N	o 1043712 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment 1043727 Activity Equipment	Bridge Burma Bridge Burma Bridge Burma Bridge Burma Bridge		No No No	15/07/2025 15/07/2025 15/07/2025 15/07/2025		67797271 67797268 67797269 67797265 67797266 67797242	There is some evidence of rot in the timber There is some wear to the shackles. The connecting lugs are showing signs of wear There is some strimmer / machinery damage apparent on the posts, this	Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace as required Monitor for any deterioration (rot) and replace as required Monitor to ensure the splits do not cross through fixing points of the Monitor to ensure the splits do not cross through fixing points of the	6 6 6 6 6	Maintenance Maintenance Maintenance Maintenance	No Grass No Grass No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes Yes No	Y: Y: Y: Y: Y:



Site Name	Site Reference	Archived	Item ID Item Type	ltem		Item Archived		Life Expectancy	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer		to P
Swanscombe Park Swanscombe Park Swanscombe Park		No	1043714 Activity Equipment 1043718 Activity Equipment 1043718 Activity Equipment	Climbing Frame Cross Chain Walk Cross Chain Walk	'B' Frame	No No No	15/07/2025 15/07/2025 15/07/2025		67797284 The paintwork on this item has been damaged or worn exposing the metal 67797250 There is some strimmer / machinery damage apparent on the posts, this 67797251 There is some notable evidence of chain wear		6 6 6	Maintenance Maintenance Maintenance	No Wet Pour No Grass No Grass	Wicksteed Playgrounds Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes Yes	<u>s</u>
Swanscombe Park		No	1043718 Activity Equipment	Cross Chain Walk		No	15/07/2025		67797252 There is some wear to the shackles.	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Grass	Playdale Playgrounds Ltd	No	,
Swanscombe Park		No	1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797294 There are gaps in excess of 30mm in the direction of travel creating foot entrapment/s in contravention of BS EN 1176 Part 1 in the bridge	Monitor - No action given the risk assessment	6	Compliance	No Wet Pour	Playdale Playgrounds Ltd	Yes	
Swanscombe Park		No	1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797295 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes	5
Swanscombe Park Swanscombe Park			1043710 Activity Equipment 1043710 Activity Equipment	Multi Play (Toddler) Multi Play (Toddler)		No No	15/07/2025 15/07/2025		67797296 There is some evidence of rot in the timber 67797297 A number of fixing(s) have worked loose	Monitor for any further deterioration and replace as required Secure all loose fixings	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	
Swanscombe Park			1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797302 Parts of the timber are rough or splintered	Remove all rough or sharp edges	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes	
Swanscombe Park			1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797292 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting proces:	Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes	
Swanscombe Park			1043717 Activity Equipment	Spring Balance Beam		No	15/07/2025		67797227 Parts of the timber are rough or splintered	Remove all rough or sharp edges	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	<u>s</u>
Swanscombe Park Swanscombe Park			1043717 Activity Equipment	Spring Balance Beam		No	15/07/2025		67797229 The paintwork on the spring has been damaged or worn exposing the meta underneath which is rusting		6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	<u>s</u>
swanscombe Park Swanscombe Park			1043725 Activity Equipment 1043725 Activity Equipment	Stepping Posts Timber Stepping Posts Timber		No No	15/07/2025 15/07/2025		67797263 There is some strimmer / machinery damage apparent on the posts, this 67797264 There is some evidence of rot in the timber	Monitor for any deterioration (rot) and replace as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	
Swanscombe Park Swanscombe Park			1043726 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797247 There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	5
swanscombe Park Swanscombe Park			1043726 Activity Equipment 1043729 Activity Equipment	Stepping Posts Timber Stepping Posts Timber		No No	15/07/2025 15/07/2025		67797248 There is some evidence of rot in the timber 67797272 There is some strimmer / machinery damage apparent on the posts, this	Monitor for any further deterioration and replace as required Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	No	
Swanscombe Park			1043729 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797273 There is some evidence of rot in the timber	Monitor for any deterioration (rot) and replace as required  Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Grass No Grass	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	
iwanscombe Park		No	1043719 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797231 There is some evidence of rot in the timber	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	•
Swanscombe Park			1043719 Activity Equipment	Stepping Posts Timber		No	15/07/2025		67797232 There is some strimmer / machinery damage apparent on the posts, this	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	
vanscombe Park			1043716 Activity Equipment	Swinging Steps		No	15/07/2025		67797261 There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the	Monitor for any deterioration (rot) and replace as required	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	í
anscombe Park			1043716 Activity Equipment	Swinging Steps		No	15/07/2025		67797259 There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	i
anscombe Park		No	1043716 Activity Equipment	Swinging Steps		No	15/07/2025		67797256 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting proces:		6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	5
anscombe Park		No	1043716 Activity Equipment	Swinging Steps		No	15/07/2025		67797257 There is some wear to the shackles.	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Grass	Playdale Playgrounds Ltd	Yes	S
anscombe Park		No	1043722 Ancillary Items	Bench		No	15/07/2025		67797183 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Grass	Glasdon	Yes	5
vanscombe Park		No	1458818 Ancillary Items	Site General		No	15/07/2025		67797187 The safety surface around the area is beginning to wear	Monitor for any further deterioration and repair as required				0/0	W	
			2 100020 111011111 111011	Site deliciti			15/07/2025		07797407 The safety surface around the area is beginning to wear	Monitor for any further deterioration and repair as required	ь	Maintenance	No N/A	Owner/Operator	<u>Yes</u>	1
nscombe Park nscombe Park			1043723 Fences 1043723 Fences	Fence - Bow Top Fence - Bow Top		No No	15/07/2025 15/07/2025		67797177 There is some damage to the fence sections 67797178 The paint is flaking off the metalwork	Monitor for any further deterioration and repair as required Rub down and re-paint	6	Maintenance Maintenance	No Grass No Grass	Unknown Unknown	Yes Yes	
										Nuo dominina re-paint	•	waintenance	NO GIASS	UIKIOWII	163	•
nscombe Park		No	1043728 Gates	Gate - Self Closing		No	15/07/2025		67797181 The paint is flaking off the metalwork	Rub down and re-paint	6	Maintenance	No Paving Slabs	Unknown	Yes	ž
ranscombe Park		No	1043711 Other	Free Standing Slide		No	15/07/2025		67797223 The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding	Treat affected areas and repaint	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	<u>s</u>
ranscombe Park ranscombe Park			1043709 Rocking Equipment 1043709 Rocking Equipment	See Saw See Saw	LNB Seesaw LNB Seesaw	No No	15/07/2025 15/07/2025		67797216 There is some wear to the pivot mechanism	Monitor for any further deterioration and repair as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	
ranscombe Park			1043709 Rocking Equipment	See Saw	LNB Seesaw	No	15/07/2025		67797217 The seat has minor damage or wear  67797218 The paintwork on this item has been damaged or worn exposing the metal	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes	
vanscombe Park		No	1043731 Rocking Equipment	Spring Bird		No	15/07/2025		67797210 The paintwork on the spring has been damaged or worn exposing the meta underneath which is rusting	I Treat any rusting components and repaint	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Ledon	<u>Yes</u> <u>Yes</u>	
vanscombe Park		No	1043731 Rocking Equipment	Spring Bird		No	15/07/2025		67797206 The item has been damaged	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Ledon	Yes	<u>s</u>
anscombe Park		No	1043731 Rocking Equipment	Spring Bird		No	15/07/2025		67797207 The end caps are missing on the Handgrips/Footrests	Replace missing end caps	6	Maintenance	No Wet Pour	Ledon	Yes	5
anscombe Park anscombe Park			1043731 Rocking Equipment 1043732 Rocking Equipment	Spring Bird Spring Horse		No No	15/07/2025 15/07/2025		67797208 The end of handgrips and/or footrests have a cross section of less than 67797213 The item has been damaged	Monitor - No action given the risk assessment  Monitor for any further deterioration and replace as required	6	Compliance Maintenance	No Wet Pour No Wet Pour	Ledon Ledon	Yes Yes	S
																*
vanscombe Park vanscombe Park			1043732 Rocking Equipment 1043724 Swings	Spring Horse 1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No No	15/07/2025 15/07/2025		67797214 The paintwork on the spring has been damaged or worn exposing the meta	Treat any rusting components and repaint	6	Maintenance	No Wet Pour	Ledon	Yes	
anscombe Park			1043724 Swings	1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No	15/07/2025		67797188 The timber has a number of splits/shakes or air cracks and this may affect 67797189 The seat has minor damage or wear	Monitor to ensure the splits do not cross through fixing points of the Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	<u>Yes</u> <u>Yes</u>	
nscombe Park		No	1043724 Swings	1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No	15/07/2025		67797190 There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes	s
anscombe Park		No	1043724 Swings	1 Bay 2 Seat (Cradle)	1.8m Timber Swing	No	15/07/2025		67797193 There is some wear to the shackles.	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	Yes	5
nscombe Park nscombe Park			1043724 Swings 1043724 Swings	1 Bay 2 Seat (Cradle) 1 Bay 2 Seat (Cradle)	1.8m Timber Swing 1.8m Timber Swing	No No	15/07/2025 15/07/2025		67797195 The seat/s is / are too close to the frame as defined in BS EN 1176 Part 2 67797196 The timber has been damaged	Monitor - No action given the risk assessment Remove all rough edges and monitor for any further deterioration and	6 6	Compliance Maintenance	No Wet Pour No Wet Pour	Playdale Playgrounds Ltd Playdale Playgrounds Ltd	Yes Yes	
nscombe Park		No	1043720 Swings	2 Bay 4 Seat (Flat)	2.4m Traditional Swin	No	15/07/2025		67797203 The swing seat connectors have some wear present	replace as required	•	Mainte	No. Was D	Walness J N		
				200, 1000 (100)	a.a moditioner awill		-5/0//2023		The swing seat connectors have some wear present	Monitor for further deterioration and replace when 40% worn	ь	Maintenance	No Wet Pour	Wicksteed Playgrounds	<u>Yes</u>	1
nscombe Park nscombe Park			1043720 Swings 1043720 Swings	2 Bay 4 Seat (Flat) 2 Bay 4 Seat (Flat)	2.4m Traditional Swin 2.4m Traditional Swin		15/07/2025 15/07/2025		67797204 There is some wear to the shackles. 67797199 The seat has minor damage or wear	Monitor for any further deterioration and replace when 40% worn Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes Yes	
ey View Play Area		No	1043773 Activity Equipment	Multi Play (Junior)	Discovery Multi-play l	No	16/07/2025		67797491 The unit is easily accessible and has an opening in the barrier to steep play		6	Compliance	No Wet Pour	Wicksteed Playgrounds	Yes	
ey View Play Area		No	1043770 Fences	Fencing - Flat Top		No	16/07/2025		elements in excess of 500mm in contravention of BS EN 1176 Part 1	Dealess all relations are	_					
ey View Play Area			1043770 Felices 1043771 Gates	Gate - Pedestrian		No	16/07/2025		67797503 A number of rails are missing 67797518 Cable ties are present and there are sharp projecting ends	Replace all missing components  Replace with a more appropriate fixing method	6	Maintenance Installation	No Grass No Concrete	Unknown Unknown	<u>Yes</u> <u>Yes</u>	
ey View Play Area			1043775 Rocking Equipment	Spring Bike	Galaxy Sit on Springle	No	16/07/2025		67797507 The end caps are missing on the Handgrips/Footrests	Replace missing end caps	6	Maintenance	No Grass Matrix Tiles	Wicksteed Playgrounds	Yes	15
r View Play Area r View Play Area			1043780 Rotor Play 1043780 Rotor Play	Roundabout Roundabout	Honeycomb Whirl Honeycomb Whirl	No No	16/07/2025 16/07/2025		67797510 The item has been damaged 67797511 The bearing is showing signs of wear	Monitor for any further deterioration and replace as required Monitor for any further deterioration and replace as required	6	Maintenance Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes	
View Play Area			1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch Sv		16/07/2025		67797499 The swing seat connectors have some wear present	Monitor for any further deterioration and replace as required Monitor for further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	<u>Yes</u> <u>Yes</u>	
ry View Play Area		No	1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch Sv	No	16/07/2025		67797500 There is some wear to the shackles.	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	š
ey View Play Area		No	1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch Sv	No	16/07/2025		67797501 The paint is flaking off the metalwork	Rub down and re-paint	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	5
		No	1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch Sv	No	16/07/2025		67797495 The seat is not level at rest	Adjust as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	5
ey View Play Area				1 0 Mind C 1 C 4 - 1 Cl- 1	2.25m Double Arch Sv	No	16/07/2025		67797496 The seat has minor damage or wear	Monitor for any further deterioration and replace as required	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	15
lley View Play Area			1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat												
lley View Play Area lley View Play Area		No	1043778 Swings	1 Bay Mixed Seat, 1 Cradle, 1 Flat	2.25m Double Arch Sv	No	16/07/2025		67797497 There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Maintenance	No Wet Pour	Wicksteed Playgrounds	Yes	25
lley View Play Area lley View Play Area comfield Recreation Ground		No No				No	16/07/2025 15/07/2025 15/07/2025		67797113 The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for	Monitor - No action given the risk assessment	6 5	Maintenance Compliance	No Wet Pour No Wet Pour	Wicksteed Playgrounds Wicksteed Playgrounds	Yes	5
alley View Play Area alley View Play Area alley View Play Area roomfield Recreation Ground roomfield Recreation Ground roomfield Recreation Ground		No No No	1043778 Swings 1043689 Activity Equipment	1 Bay Mixed Seat, 1 Cradle, 1 Flat Climbing Frame	2.25m Double Arch Sv Delta Climber	No No	15/07/2025			Monitor - No action given the risk assessment Monitor - No action given the risk assessment	6 5 5 5	Maintenance	No Wet Pour	Wicksteed Playgrounds		5



1	Part Number Item Inspection Life Expectancy Finding ID Finding Details Remedial Action Risk Finding Type Priority Surface Manufacturer Factor Factor	Finding Photo
	of the current applicable standard	Yes
Marchanes   10   Windows   10   Wi		Yes
1	2.8m Traditional Swin No 15/07/2025 67797108 The surfacing width under the seat/s is / are less than 875mm when Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds measured from the centre of the seat outwards, and fail the requirements	<u>Yes</u>
Company	2.8m Traditional Swin No 15/07/2025 67797111 The surfacing dimensions are short and do not meet with the requirements Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds	Yes
March   Marc	No 15/07/2025 67797083 The chain openines are in excess of the 8.6mm as recommended by BS EN Monitor - No action given the risk assessment 5 Compliance No Grass Matrix Tiles Playdale Playgrounds L'	Yes
	No 16/07/2025 67797566 The gate is not operating correctly Take effective action to ensure the gate closes between 4 and 8 seconds 5 Maintenance No Mixed Surface Unknown	Yes
1	The Entering action of Entering Contents and Section of Entering Contents and Section of Contents action of	Yes Yes
Marche   M	No 15/07/2025 67797447 The Item fails to meet the requirements of BS EN 1176 Part 14.2.7.2 head Monitor - No action given the risk assessment 5 Compliance No Wet Pour Playdale Playgrounds Lt	Yes
Part		Yes Yes
1	recommendations set out in BS EN 1176 Part 1  No 15/07/2025 67797472 The surfacing dimensions are short and do not meet with the requirements Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds	Yes
Part	1176	<u>Yes</u> <u>Yes</u>
March   Marc	of the current applicable standard	Yes
1	2.1m Double Arch Swi No 15/07/2025 67797310 The chain openings are in excess of the 8.6mm as recommended by BS EN Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds	<u>Yes</u>
1	Lightly forth white the state of the state o	Yes
1		Yes
1		Yes
1	No 15/07/2025 67797422 The gate is not operating correctly Take effective action to ensure the gate closes between 4 and 8 seconds 5 Maintenance No Tarmac Unknown	<u>Yes</u>
See		Yes
1		Yes
1		Yes
10   10   10   10   10   10   10   10		Yes
State   Stat		Yes Yes
1000   1000		Ye
Part	head and neck entrapment in the net	Ye
Part	of the current applicable standard	<u>Ye</u>
Part	space of the equipment, in contravention of the requirements of BS EN	<u>Yes</u>
March   Marc	No 15/07/2025 67797221 There is / are toggle entrapment/s present in contravention of the Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds	Yes Yes
1		Yes
1   1   1   1   1   1   1   1   1   1		Yes No
1		Ye
1	2.4m Traditional Swin No 15/07/2025 67797202 The chain openings are in excess of the 8.6mm as recommended by BS EN Monitor - No action given the risk assessment 5 Compliance No Wet Pour Wicksteed Playgrounds	Ye
Second Control Contr		Y
Second content of the content of t		Ye
1   1   1   1   1   1   1   1   1   1	Delta Climber No 15/07/2025 67797118 There is some minor damage to the surface Monitor for any further deterioration and repair as required 4 Maintenance No Wet Pour Wicksteed Playgrounds	<u>Ye</u> Ye
1   1   1   1   1   1   1   1   1   1	No. 15/07/2025 67797089 This item is satisfactory - no work required 4 Satisfactory No. Grass Playdale Playgrounds I	Y
Part	No 15/07/2025 67797085 There is/are bolt cap covers missing or damaged on the item Replace missing or damaged bolt cap covers 4 Maintenance No Grass Matrix Tiles Playdale Playgrounds Li	Y
No.   10,000   10,0		Y
Second   S	Glow worm No 15/07/2025 67797120 There is some minor damage to the surface Monitor for any further deterioration and repair as required 4 Maintenance No Wet Pour Wicksteed Playgrounds	Y
Second Control Contr	No 15/07/2025 67797129 There is/are bolt cap covers missing or damaged on the Item Replace missing or damaged bolt cap covers 4 Maintenance No Mixed Surface Ledon	Ye
100-1986    100-		Y
Equip Sead File   April   Equip Sead File   April   Sead File   Sead File   April   Sead File   Sea		<u>Y</u>
Eagles Noad   No   1043705   Accillary Name   No   1043705	No 16/07/2025 67797547 There is/are bolt cap covers missing or damaged on the item Replace missing or damaged bolt cap covers 4 Maintenance No Grass Matrix Tiles A.E.Evans	<u>Y</u> .
Lighes Road Flay Area		<u>Y</u>
Eagles Road Play Area  No 1043802 Ancillary tenns  No 1043802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 1043802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 1043802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 1043802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 104802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 104802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 104802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 104802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Area  No 104802 Swings  Basket Swing - Type 1 2.3m Timber Swing Register Road Play Register Road Play Register Register Road Play Register Register Road Play Register Road Pl		Ye
Heritage Park No 118578 Activity Equipment Activity Trail No 15/07/2025 G7797125 There is/are bolt cap covers missing or damaged on the item Missing or damaged bolt cap covers Missing or dama		Ye Ye
Satisfactory   No   186754   Accillary Nems   186755   Fences   No   15/07/2025   67797128   This tem is satisfactory - no work required   4 Satisfactory No   67635   Unknown Nems   186755   Fences   No   186755   Fences   Pluground Sign   No   15/07/2025   67797158   This tem is satisfactory - no work required   4 Satisfactory No   67635   Unknown Nems   No   186755   Fences   Pluground Sign   No   15/07/2025   67797158   This tem is satisfactory - no work required   4 Satisfactory No   67635   Unknown Nems   No   186755   Fences   Pluground Sign   No   15/07/2025   67797158   This tem is satisfactory - no work required   4 Satisfactory No   67635   Unknown Nems   No   186755   Fences   Pluground Sign   No   15/07/2025   67797158   This tem is satisfactory - no work required   4 Satisfactory No   No   No   No   No   No   No   No		
Heritage Park Ho 18676 Fences Fence No 186756 Fences Fence No 186756 Fences Fence No 186756 Fences Fence No 186756 Fences Fence No 186757 Signs Playground Sign No 19672025 F797161 No 19672025 F797162 Fris item is satisfactory - no work required Monitor for any further deterioration and repair as required No 1043759 Activity Equipment Multi Play (Senior) No 1043756 Activity Equipment Multi Play (Senior) No 15/07/2025 F797480 Fine rear an unmber of definits in the slides surface Monitor for any further deterioration and repair as required No 1043752 Activity Equipment No 1043764 Ancillary Items Multi Play (Senior) No 15/07/2025 F797480 Fine rear an unmber of definits in the slide surface Monitor for any further deterioration and repair as required No 1043764 Ancillary Items Multi Play (Senior) No 1043764 No 1043767 Multi Play (Senior) No 15/07/2025 F797480 Fine rear an unmber of definits in the slide surface Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further deterioration and repair as required Monitor for any further dete		<u>Y</u> <u>Y</u>
Heritage Park He		Y
Rent Reger at Nation Control (1943759) Activity Equipment (194198) No 15/07/2025 6779458 There are a number of dents in the slide surface (19418) Monitor for any further deterioration and repair as required (19418) Activity Equipment (19418) Recreation Ground (1943759) Activity Equipment		2
Knockhall Recreation Ground No 1043752 Activity Equiment No 15/07/2025 6779442 No 1043764 Ancillary Items No 1043764 Ancillary Items No 1043767 Ancillary It		2
Knockhall Recreation Ground No 1043752 Activity Equiment No 15/07/2025 6779442 No 1043764 Ancillary Items No 1043764 Ancillary Items No 1043767 Ancillary It	No 15/07/2025 67797459 There is/are bolt cap covers missing or damaged on the item Replace missing or damaged bolt cap covers 4 Maintenance No Wet Pour Plaudale Plaverounds 1	
Knockhall Recreation Ground  No 1043767 Ancillary Items  Bench  No 15/07/2025  67797481 This item is satisfactory - no work required  A Satisfactory No Mixed Surface  Unknown  Knockhall Recreation Ground  No 1043762 Fences  Fence - Bow Top  No 15/07/2025  67797482 This item is satisfactory - no work required  A Satisfactory No Grass  Unknown	No 15/07/2025 67797442 There are a number of dents in the slide surface Monitor for any further deterioration and repair as required 4 Maintenance No Wet Pour Playdale Playgrounds L	
Knockhall Recreation Ground  No 1043762 Fences  Fence - Bow Top  No 15/07/2025  67797439 This item is satisfactory - no work required  4 Satisfactory No Grass  Unknown		ž.
And and neutration distance and a second and		<u>Y</u>
Knockhall Recreation Ground No 1043751 Other Free Standing Slide No 15/07/2025 67797474 There are a number of dents in the slide surface Monitor for any further deterioration and repair as required 4 Maintenance No Wet Pour Wicksteed Playgrounds		<u> </u>



ID Site Name	Site Reference	Site Item ID Item Type Archived	Item	Part Number	Item Archived	Inspection Date	Life Expectancy	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Type	Priority Surface	Manufacturer	Findi Phot
57 Knockhall Recreation Ground	 	No 1043748 Swings	2 Bay (2 Flat, 2 Cradle)	2.3m Swing	No	15/07/2025		67797455	There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Maintenance	No Wet Pour	Caloo	Ye
Manor Park		No 1043737 Activity Equipment	Multi Play (Junior)		No	15/07/2025		67797315	There is some minor damage to the surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Setter Play	Ye
Manor Park		No 1043737 Activity Equipment	Multi Play (Junior)		No	15/07/2025		67797324	There are a number of dents in the slide surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Setter Play	Ye
Manor Park		No 1043742 Activity Equipment	Stepping Stones		No	15/07/2025			This item is satisfactory - no work required	months for any factors determined and report of required	4	Satisfactory	No Grass	Not Identified	Ye
Manor Park		No 1043741 Ancillary Items	Bench		No	15/07/2025		67797336	This item is satisfactory - no work required		4	Satisfactory	No Paving Slabs	Glasdon	Ye
Manor Park		No 1043739 Signs	Playground Sign		No	15/07/2025		67797353	This item is satisfactory - no work required		4	Satisfactory	No N/A	Not Identified	Ye
Manor Park		No 1043734 Swings	1 Bay 2 Seat (Flat)	2.1m Double Arch Sw	i No	15/07/2025			The bush / bushes is / are showing signs of wear	Monitor for any further deterioration and replace as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	Ye
Saxon Court Play Area		No 1043831 Activity Equipment	Multi Play (Junior)	Zigzag Tower & Slide		15/07/2025			There are a number of dents in the slide surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	Ye
Saxon Court Play Area		No 1043816 Ancillary Items	Bench		No	15/07/2025		67797364	This item is satisfactory - no work required			Satisfactory	No Mixed Surface	Glasdon	Y
Saxon Court Play Area		No 1043830 Ancillary Items	Litter Bin		No	15/07/2025			This item is satisfactory - no work required		7	Satisfactory	No Grass	Glasdon	2
axon Court Play Area		No 1043811 Fences	Fence - Bow Top		No	15/07/2025			This item is satisfactory - no work required		4		No Grass	Unknown	
Saxon Court Play Area		No 1043824 Fences	Fencing - Timber		No	15/07/2025					4	Satisfactory			
and the state of t									This item is satisfactory - no work required		4	Satisfactory	No Grass	Unknown	
Swanscombe Park		No 1043712 Activity Equipment	Bridge		No	15/07/2025			There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Maintenance	No Grass	Playdale Playgrounds Ltd	
Swanscombe Park		No 1043730 Activity Equipment	Chain Traverse		No	15/07/2025			There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Maintenance	No Grass	Playdale Playgrounds Ltd	
wanscombe Park		No 1043714 Activity Equipment	Climbing Frame	'B' Frame	No	15/07/2025			There is some minor damage to the surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	
Swanscombe Park		No 1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797291	There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
Swanscombe Park		No 1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797298	There are a number of dents in the slide surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
Swanscombe Park		No 1043706 Ancillary Items	Litter Bin		No	15/07/2025		67797184	This item is satisfactory - no work required		4	Satisfactory	No Grass	Glasdon	
Swanscombe Park		No 1043711 Other	Free Standing Slide		No	15/07/2025		67707220	There are a number of dents in the slide surface	Monitor for any further deterioration and repair as required		Maintenance	No Wet Pour	Wicksteed Playgrounds	
		No 1043731 Rocking Equipment	•		No	15/07/2025									
wanscombe Park			Spring Bird						There is some minor damage to the surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Ledon	
wanscombe Park		No 1043732 Rocking Equipment	Spring Horse		No	15/07/2025			There is some minor damage to the surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Ledon	
Swanscombe Park		No 1043707 Signs	Playground Sign		No	15/07/2025		67797179	This item is satisfactory - no work required		4	Satisfactory	No N/A	Not Identified	
Swanscombe Park		No 1043720 Swings	2 Bay 4 Seat (Flat)	2.4m Traditional Swir		15/07/2025		67797205	The bush / bushes is / are showing signs of wear	Monitor for any further deterioration and replace as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	
Valley View Play Area		No 1043773 Activity Equipment	Multi Play (Junior)	Discovery Multi-play	l No	16/07/2025		67797487	There is some minor damage to the surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	
Valley View Play Area		No 1043773 Activity Equipment	Multi Play (Junior)	Discovery Multi-play	l No	16/07/2025		67797488	There are a number of dents in the slide surface	Monitor for any further deterioration and repair as required	4	Maintenance	No Wet Pour	Wicksteed Playgrounds	
Valley View Play Area		No 1043785 Activity Equipment	Multi Play (Toddler)	Nursery Rhyme Towe	ei No	16/07/2025		67797506	This item is satisfactory - no work required		4	Satisfactory	No Grass Matrix Tiles	Wicksteed Playgrounds	
Valley View Play Area		No 1043777 Activity Equipment	Play Panel		No	16/07/2025			This item is satisfactory - no work required		,	Satisfactory	No Grass	Wicksteed Playgrounds	
Valley View Play Area		No 1043783 Activity Equipment	Play Panel		No	16/07/2025			This item is satisfactory - no work required					Wicksteed Playgrounds	
		No 1043779 Ancillary Items	Litter Bin			16/07/2025					4	Satisfactory	No Grass		
Valley View Play Area					No				This item is satisfactory - no work required		4	Satisfactory	No Grass	Glasdon	
Valley View Play Area		No 1043774 Ancillary Items	Seat		No	16/07/2025			This item is satisfactory - no work required		4	Satisfactory	No Grass	Glasdon	
Valley View Play Area		No 1043772 Fences	Fence		No	16/07/2025		67797513	This item is satisfactory - no work required		4	Satisfactory	No Grass	Unknown	
Valley View Play Area		No 1043776 Fences	Fence - Bow Top		No	16/07/2025		67797514	This item is satisfactory - no work required		4	Satisfactory	No Grass	Unknown	
												,			
Valley View Play Area		No 1043784 Signs	Playground Sign		No	16/07/2025		67797493	This item is satisfactory - no work required		4	Satisfactory	No N/A	Not Applicable	
Broomfield Recreation Ground		No 1043689 Activity Equipment	Climbing Frame	Delta Climber	No	15/07/2025		67797115	There is some graffiti present	Remove the graffiti	0	Vandalism	No Wet Pour	Wicksteed Playgrounds	
Broomfield Recreation Ground		No 1043685 Activity Equipment	Multi Play (Junior)		No	15/07/2025			There is offensive graffiti present	Remove as soon as practicable	0	Vandalism	No Wet Pour	Playdale Playgrounds Ltd	
Broomfield Recreation Ground		No 1043685 Activity Equipment	Multi Play (Junior)		No	15/07/2025			The ropes on this item have been taped and we are unable to fully assess		0	Maintenance	No Wet Pour	Playdale Playgrounds Ltd	
Broomfield Recreation Ground		No 1043680 Other	Free Standing Slide	High Pedestal Slide	No	15/07/2025			There is offensive graffiti present	Remove as soon as practicable	0	Vandalism	No Wet Pour	Wicksteed Playgrounds	
Eagles Road Play Area		No 1043801 Activity Equipment	Traverse Ropes	Traversing Nets & Wa	a No	16/07/2025		67797560	There is some graffiti present	Remove the graffiti	0	Vandalism	No Grass Matrix Tiles	A.E.Evans	
Eagles Road Play Area		No 1043799 Gates	Gate - Maintenance		No No	16/07/2025			The maintenance gate was correctly padlocked at the time of inspection,		0	Installation	No Grass Matrix files	Unknown	
Eagles Road Flay Area		1043733 Gates	Cate - Maintenance		110	10/07/2023			however this means that the inspector was unable to fully assess the gate		Ü	installation	NO Grass	Unknown	
Knockhall Recreation Ground		No 1043759 Activity Equipment	Multi Play (Senior)		No	15/07/2025		67797464	There is offensive graffiti present	Remove as soon as practicable	0	Vandalism	No Wet Pour	Playdale Playgrounds Ltd	
Manor Park		No 1043737 Activity Equipment	Multi Play (Junior)		No	15/07/2025		67797323	There is offensive graffiti present	Remove as soon as practicable	0	Vandalism	No Wet Pour	Setter Play	
Manor Park		No 1043744 Gates	Gate - Maintenance		No	15/07/2025			The maintenance gate was correctly padlocked at the time of inspection, however this means that the inspector was unable to fully assess the gate		0	Installation	No Grass	Not Identified	
Manor Park		No 1043743 Gates	Gate - Pedestrian		No	15/07/2025			The gate/s was / were locked or secured at the time of the inspection and a		0	Compliance	No Grass	Unknown	
					-				full inspection could not be undertaken		•	compliance	0.033		
Swanscombe Park		No 1043710 Activity Equipment	Multi Play (Toddler)		No	15/07/2025		67797300	There is some graffiti present	Remove the graffiti	0	Vandalism	No Wet Pour	Playdale Playgrounds Ltd	
		No 1043731 Rocking Equipment	Spring Bird		No	15/07/2025			There is some graffiti present	Remove the graffiti	0	Vandalism	No Wet Pour	Ledon	
Swanscombe Park															
Swanscombe Park Valley View Play Area		No 1043781 Gates	Gate - Maintenance		No	16/07/2025		67797509	The maintenance gate was correctly padlocked at the time of inspection	Ensure that there are 12mm gaps throughout the full range of motion on	0	Installation	No Mixed Surface	Unknown	